

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 199607198R GST Reg. No. 19-9607198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref:	CS/AGI24120113/Unh3m4(N)	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Date	: 03/01/2025	
	ATTN: VENESSA	CHAN	Code	e: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJU 8682A	Veh. Inspected	SMK 3733L	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10033295/VC	Excess (\$)	0.00	
	Assign From	LAN BOON CHIN	Assign Date	09/12/2024	
2.	2. Vehicle Particulars & Condition				
	Make & Model	HONDA VEZEL 1.5G (A)	C.C	1496	
	Engine No.	HIDDEN	Year of Reg.	2022	
	Chassis No.	RV31010024	Colour	GREY	
	Odometer	62109 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/55R17	MICHELIN	6 mm	
	L/H Front Tyre	225/55R17	MICHELIN	6 mm	
	R/H Rear Tyre	225/55R17	MICHELIN	6 mm	
	L/H Rear Tyre	225/55R17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	04/12/2024	Inspection Date	09/12/2024	
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: