
ASS. REC. BY: Taufth - REF: CS CT12	412 0115 Tgh 3
ASSI	GNMENT
From: Date:	Veh No: SGX3366R Yr Regn: 2021 103
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD / PI WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: 13MW 2181 c.c 1499
at Workshop m/s	Colour Red A/C: Insured / Std / NI / NA
of	Sp.Reading 42344 T/Radio; Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WBA12AK 00.07440981
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorden/ Jammed / Leaked / Burnt or
Make of Veh:	Modl: NII / SRin / STD A/Rim or
	Tyre Size: F: 225/45817
(Policy Condition)	K:
Remark: The veh had commenced its N/S O/S	BS JOUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection. \$1151	TOYO / YOKO or
Dat of Indian 1944	- Front Rear R/Bal. 6 mm
IDAC Accident Roort Consistent? : Yes or No	Typed, Typed Typed
GIA / PR Seen: Consistent? : Yes or No	D.O.A. D.O.I. 08/1/25
Est Repairs: days Res.: Yes or No	
Lum Sum: % 3 Val.: Yes or No	Des. of Damages : Frt / Rear O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	1 714 311
Date: Person Contacted: Hong 79	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
1	
Communication of the Communica	Days Of Repair:
Date/Time, File Pass 107 : Prell. Report	
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to? Add F.	
<u>2)</u>	: Interview (\$) Photos
The same of Fernandari	: Tech. Invs (\$) offices
Reput Format :	: Weel end (\$
Lump Sum / LBJ: (F)	
	TOTAL



BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad

(AfterSales) (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

CHINA TAIPING 06 DEC 2024

Estimate No. : b1 72040 Date Estimated : 06/12/2024 : Tee Hong Da Prepared By

- ESTIMATE REPAIR FOR -Thangam D/O Krishnan

1E Green Lane

40000 - ACCOUNT -

Cash Sales - Service

Singapore

Singapore 438891

. }

2

Q

REGN. NO. CHASSIS NO. REGN. DATE

MODEL

MILEAGE

Page No. : 1 of 5

23/03/2021 SGX3366R WBA12AK0007H40981

2181 Gran Coupe

39537

DESCRIPTION To replace front bumper, make good front right fender, front right driver door and attachement	1700 3,400.00
To respray front bumper. front right fender , front right door, front right door handle, and attachment	1923 2,882.00
To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).	531.00
To check electrical wiring system at the front section for proper function.	/ 177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	✓ 177.00
Sundries.	7 150.00

Total Labour 1:

7,317.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 7.5JX17 DOUBLE SPK 548	1	998.60	cut/998.60
IMPACT ABSORBER TOP	1	89.60	★ 89.60
RH FOG LAMP SUPPORT	1	144.55	× 144.58
FRT BUMPER BOTTOM CARRIER	1	177.80	× 177.80
RH FOG LAMP COVER	1	50.75	cut 50.7!
FRT BUMPER PANEL PRIMED (PDC/PMA)	1	987.80	de~ 987.80
SET MOUNTING PDC/PMA SENSOR FRT	1	75.55	NU-75.5
DECOUPLING RING	1	5.65	ner 5.6
Ultrasonic s	1	391.05	7 391.0
	Tot	al Parts	: 2,921.3

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 64796624

GST REG. NO: M2 - 0020081 - X

ESTIMATE

Estimate No.

Date Estimated

: b1 72040

: 06/12/2024

Prepared By

: Tee Hong Da

Page No. : 2 of 5

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SGX3366R

WBA12AK0007H40981

23/03/2021

218i Gran Coupe

39537

Taylin 97495749 (62563561 WP' 08/01/24 210304-Plf Rearney before paint taufin elhhanto.com. 5-6days

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damageo part(s) during resurvey
- · Parts prices are subject to confumation
- . Third party survey is on a " with" it Prejudice" basis
- No illegal modification(s) is so less.
- Supplementary liem(s) mis accorded and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1 Parts

Labour 2 Excess

Total GST @ 9%

7,317.00 2,921.35 0.00

0.00 921.45

Grand Total

11,159.80

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY** ** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOU

SP0X24C2000F / Performance Motors Limited ENTRY DATE & TIME: 02/12/2024 19:46 (SGT) SUBMITTED BY: Wong Hui Min VERSION: 1 (02/12/2024 19:46 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENTISTATEMENT Date of First Submission 02/12/2024 19:46 (SGT) Reported by **Actual Driver** Date of Accident 29/11/2024 13:42 (SGT) Exact Location of Accident ... 2A Green Ln, Singapore 438893 Additional Location Information Country/State of Loss Singapore Vehicle Registration Number SGX3366R Is company? Name Of Registered Owner THANGAM D/O KRISHNAN SXXXX823H Email Address ... malakrishnan08@gmail.com (Phone) +65-98713089 VEHICLE PARTICULARS Manufacturer . . **BMW** Model 218i Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto CC 1499 Vehicle Fuel First Regisration Date Chassis no Effective Date/Time of Ownership

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd. 7220018117-02

DRIVER



lame of Driver NRIC No Date Of Birth Decupation Driving Pass Date Driving License Pass Class Driving License Validity Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles?	SIM SIEW JOO SXXXX508H 28/01/1968 Indoor 13/03/1997 3 Valid 27 YEARS AND 8 MONTHS Female (Phone) +65-97312688 - judysjsim@gmail.com 1E GREEN LANE - 438891 No Relative No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	•
GENERAL INFORMATION OF THE ACCIDENT	(고현 왕조) (1 전 화장 제로 1 조 조 조 교육 1 전 1 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기 기
Type of Accident Weather Conditions Road Surface	Hit and run / Vandalism / Damaged whilst parked Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement	No 2 No - Yes 0 No
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No
CIRCUMSTANCES OF ACCIDENT	
PLEASE REFER TO ATTACHED SKETCH PLAN.	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera?	Yes No
DETAILS OF OTHER	VEHICLE PROBERTY
Vehicle Registration Number	
Vehicle Manufacturer	SMG8298P

Accident report SP0X24C2000F

Page 2 at to

Vehicle Model	_
Vehicle Variant	
Vehicle Colour	
Vehicle Category	Private car
Name of Driver	YUAN KAI
Contact Number	
Contact Number	(Phone) +65-90625839
Address	
Address complement	>=
Postcode	-
Insurance Company Name	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage	*
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 Interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of the purpose(s).
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature (if driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature

Name: Tee Hong Da
NRRAMMance Motors Limited
303 Alexandra Road
Sima Darby Performance Centre
Singapore 159941

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/11/24 at ground 3:50 pm, I received a call and a
ploto note image from my helper. The note stated that
my consins on was scratched by another car and
to contact a "Yuan" (please see the handwrittee note)
As my consin was overcoas on heliday, and I was also in
Milaysia or Vacation I asked my helper to take placed
of the demage to my consins on
I then subsequently managed to contact the other
of the demage to my cousin's chip. If then sirtseque atten managed to contact the other driver, his name is! Your Kai and he gave me his
driving too close to it to avoid author mother car by
driving too close to it to avid another car.
Twinformation, my cousins car was parked stickness
They for gave me the line of the incident and
Managed to retrieve the conterna video . Inclosed
vided for your information (time: 142 pm).
DECLARATION
/We declare the foregoing particular, and the

Time deciare the foregoing particulars are true in every respect

Policyholder's Signature Date & Time

Driver's Signature

(If driver is not the policyholder).
Date & Time

Reporting Centre P.S. Hong De Name, Performance Motors Liffilled NRIC/FIN No.303 Alexandra Road Sime Darby Performance Centre Singapore 159941