

ASS. REC. BY: Taufik

REF: CS/CT12412 0115/Tgh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$115K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Hong Da Vehicle: IN / OUT

Veh No: S9X3366R Yr Regn: 2021 / 03

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 2181 c.c. 1499

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 42344 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA12AK 00.07H40981

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 08/1/25

Survey held at Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised final fig \$6757.40, 6 days (Red \$3663.95, 35%)

Date/Time, File Pass to? ☐ : Prell. Report

1) 12/02 Typist ☐ : Final Report

Date/Time, File Return to?

2) _____

Rep. Format: _____

~~Lump Sum~~ / L.B.I. (\$) 6757.40)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Photos _____

Others _____

TOTAL _____

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

CHINA TAIPIING

06 DEC 2024

Page No. : 1 of 5

Estimate No. : b1 72040
Date Estimated : 06/12/2024
Prepared By : Tee Hong Da

- ESTIMATE REPAIR FOR -
Thangam D/O Krishnan
1E Green Lane

Singapore 438891

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX3366R	WBA12AK0007H40981	23/03/2021	2191 Gran Coupe	39537

DESCRIPTION**VALUE**

To replace front bumper, make good front right fender, front right driver door and attachment

1700 3,400.00

To respray front bumper, front right fender, front right door, front right door handle, and attachment

1923 2,882.00

To check steering geometry and conduct wheel alignment in accordance with BMW specifications. (1x).

✓ 531.00

To check electrical wiring system at the front section for proper function.

✓ 177.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.

✓ 177.00

Sundries.

? 150.00

Total Labour 1: 7,317.00

DESCRIPTION**QTY****PRIC****VALUE**

ALLOY RIM 7.5JX17 DOUBLE SPK 548

1

998.60

cut ✓ 998.60

IMPACT ABSORBER TOP

1

89.60

x 89.60

RH FOG LAMP SUPPORT

1

144.55

x 144.55

FRT BUMPER BOTTOM CARRIER

1

177.80

x 177.80

RH FOG LAMP COVER

1

50.75

cut ✓ 50.75

FRT BUMPER PANEL PRIMED (PDC/PMA)

1

987.80

de ✓ 987.80

SET MOUNTING PDC/PMA SENSOR FRT

1

75.55

rel ✓ 75.55

DECOUPLING RING

1

5.65

rel ✓ 5.65

Ultrasonic s

1

391.05

? 391.05

Total Parts : 2,921.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 72040
Date Estimated : 06/12/2024
Prepared By : Tee Hong Da

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGX3366R	WBA12AK0007H40981	23/03/2021	218i Gran Coupe	39537

Tanjin 97495749/62563561
- wp' 08/01/24 @ 1030pm
p/f Resurvey before paint
tanjin ekkhanto.com.
5-6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	7,317.00
Parts	:	2,921.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	921.45
Grand Total	:	11,159.80

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT NOTICE

72040

SPOX24C2000F / Performance Motors Limited
ENTRY DATE & TIME: 02/12/2024 19:46 (SGT)
SUBMITTED BY: Wong Hui Min
VERSION: 1 (02/12/2024 19:46 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	02/12/2024 19:46 (SGT)
Reported by	Actual Driver
Date of Accident	29/11/2024 13:42 (SGT)
Exact Location of Accident	2A Green Ln, Singapore 438893
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF VEHICLE

Vehicle Registration Number	SGX3366R
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	THANGAM D/O KRISHNAN
NRIC No	SXXXX823H
Email Address	malakrishnan08@gmail.com
Mobile Phone No	(Phone) +65-98713089
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	218i
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1499
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7220018117-02

DRIVER

Name of Driver	SIM SIEW JOO
NRIC No	SXXXX508H
Date Of Birth	28/01/1968
Occupation	Indoor
Driving Pass Date	13/03/1997
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	27 YEARS AND 8 MONTHS
Gender	Female
Mobile Number	(Phone) +65-97312688
Alt. Phone Number	-
Email Address	judysjsim@gmail.com
Address	1E GREEN LANE
Address complement	-
Postcode	438891
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Relative
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SMG8298P
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	YUAN KAI
Contact Number	(Phone) +65-90625839
Address	-
Address complement	-
Postcode	-
Insurance Company Name	China Taiping Insurance (Singapore) Pte. Ltd.
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: Tee Hong Da
NRR Performance Motors Limited
303 Alexandra Road
Sims Darby Performance Centre
Singapore 159941

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 29/11/24 at around 3:50pm, I received a call and a photo note image from my helper. The note stated that my cousin's car was scratched by another car and to contact a "Yuan". (please see the handwritten note)

As my cousin was overseas on holiday, and I was also in Malaysia on vacation, I asked my helper to take photos of the damage to my cousin's car.

I then subsequently managed to contact the other driver, his name is Yuan Kai and he gave me his car plate number and said he scratched the car by driving too close to it to avoid another car.

For information, my cousin's car was parked stationary. Yuan Kai gave me the time of the incident and I managed to retrieve the camera video. Enclosed video for your information (time: 142pm).

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Person's Signature
Name, Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941