

ASS. REC. BY:

REF: F021

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cohd: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Rear

R/Bal.

L/Bal.

D.O.I.

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

F - RS

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 20006485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Repair Estimates

SMH 8724 X

Parts	(a) Cost / List Price Items	\$	23,658.07
	Plus/Less 25%	\$	5,914.52
	Total of Cost / List	\$	29,572.59
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	700.00
Total Parts Cost		\$	30,272.59
Labour		\$	4,140.00
Total		\$	34,412.59

The above total will be subjected to 9% G.S.T.

Not Authorized
1/1 Png &
Repair After Paint

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Be

Date: 10/12/24



ESTEEM

ESTEEM PERFORMANCE PTE LTD
UEN 200005485N

HEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394

WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SMH8724X

TOYOTA CAMRY 4-DOOR SEDAN (AUTO) 2.0
MR2BN3HK704001813

Submit By :

Year Manufacture :

Engine No. :

13-Feb-19

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front fender <i>R</i>	1	\$1,318.90		✓
2	LH front fender undershield <i>Sn</i>	1	\$392.00		X
3	LH front fender undershield clip <i>na</i>	10	\$50.00		X
4	LH front door <i>Rt/warp</i>	1	\$2,573.90		✓
5	LH front door hinge top <i>R</i>	1	\$135.40		X
6	LH front door hinge bottom <i>R</i>	1	\$135.40		X
7	LH front door lock <i>R</i>	1	\$840.30		X
8	LH front door checker <i>Sn</i>	1	\$305.00		X
9	LH front door weatherstrip <i>Sn</i>	1	\$335.00		X
10	LH front door trim <i>Sn</i>	1	\$1,581.30		X
11	LHF door glass outer moulding <i>Sn</i>	1	\$227.70		X
12	LHF power window motor <i>Sn</i>	1	\$1,273.00		X
13	LHF power window regulator <i>Sn</i>	1	\$354.50		X
14	LH rear door <i>Rt/warp</i>	1	\$2,236.20		✓
15	LH rear door hinge top <i>R</i>	1	\$135.40		X
16	LH rear door hinge bottom <i>R</i>	1	\$135.40		X
17	LH rear door lock <i>R</i>	1	\$779.30		X
18	LH rear door weatherstrip <i>Sn</i>	1	\$311.67		X
19	LH rear door trim <i>Sn</i>	1	\$1,331.90		X
20	LHR door glass outer moulding <i>Sn</i>	1	\$157.50		X
21	LHR power window motor <i>Sn</i>	1	\$1,273.00		X
22	LHR power window regulator <i>Sn</i>	1	\$341.70		X
23	LH rear fender <i>R</i>	1	\$1,559.40		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SMH8724X

TOYOTA CAMRY 4-DOOR SEDAN (AUTO) 2. (Year Manufacture :
MR2BN3HK704001813

Submit By :
Engine No. :

0
43509

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH rear fender undershield	1	\$272.80		X
25	LH rear fender undershield clip	10	\$50.00		X
26	LH front rim	1	\$2,775.70		X
27	LH front tyre	1	\$350.00	SN	X
28	LH rear rim	1	\$2,775.70		7
29	LH rear tyre	1	\$350.00	SN	X
30					
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

If any of the quoted parts are recommended to be repaired, then an additional labour charge be charged accordingly under supplementary.

**ESTEEM**ESTEEM PERFORMANCE PTE LTD
UEN 200005485NHEADQUARTERS / SHOWROOM / WORKSHOP
385 Sin Ming Drive
Singapore 575718
(T) 6753 2112 (F) 6451 0394WORKSHOP
176 Sin Ming Drive
Sin Ming Auto Care #01-14, #01-15, #01-16
Singapore 575721
(T) 6484 1221 (F) 6484 7829**Labour**Vehicle No. : **SMH8724X** Submit By : **0**
Make & Model : **CAMRY 4-DOOR SEDAN (AUTO)** Year of Manufacture : **13-Feb-19**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM)	\$1,600.00	700
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(FRONT BUMPER,LHF FENDER,LHF DOOR,LHR DOOR,LHR FENDER,REAR BUMPER,LHF RIM,LHR RIM)	\$1,600.00	1200
3	To check wiring	\$50.00	20
4	To do wheel alignment.	\$120.00	60
5	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.	\$150.00	120
6	To tuff coat.	\$200.00	90
7	To remove & refit inner seat & upholstery to assist work load. <i>nn</i>	\$150.00	X
8	To remove & refit roof lining, inner trim to assist work load. <i>nn</i>	\$150.00	X
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 06/12/2024 09:39 (SGT)
Reported by Owner
Date of Accident 05/12/2024 11:30 (SGT)
Exact Location of Accident Balmoral Rd, Singapore
Additional Location Information -
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMH8724X

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner GOLDBELL CAR RENTAL PTE LTD
Company Reg No 2XXXXX651D
Email Address accident@gbcr.com.sg
Mobile Phone No (Phone) +65-66039398
Alternative Phone No -

VEHICLE PARTICULARS

Manufacturer Toyota
Model Camry
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1998
Vehicle Fuel -
First Registration Date -
Chassis no -
Effective Date/Time of Ownership -

INSURANCE COMPANY

Name of Insurance Company Tokio Marine Insurance Singapore Ltd
Policy Number / Cover Note Number 24-MAB00157-R00

DRIVER

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as initial and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to revisit a policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the Insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as in the external cover of envelopes/mailed packages) and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

SOH JIT HOON
Rec'd 05 DEC 2024

Sketch Plan