

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internationa	le Des Experts En	Automobile
Y INSURAN	CE PTE LTD	Ref:	CS/LIP24120133/Knh3m4
ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	19/12/2024
PORE 04858	3	Code:	LIP
	Policy Particulars :- THIRD PARTY (CLAIM (PHYSICAL	REINSPECTION)
d Veh.	SNL 2559M	Veh. Inspected	SMH 1691C
No.	-	Coverage	0
No.	BVS24/0236	Excess	\$0.00
From	PATRICK YONG	Assign Date	10/12/2024
2. Vehicle Details			
Model	VOLKSWAGEN TOURAN (A)	C.C	1390
No.	CAV245542	Year of Reg.	24/01/2011
s No.	WVGZZZ1TZBW043224	Colour	METALLIC BROWN
ter	292065 KM	Steering	IN ORDER
	IN ORDER	General	GOOD
ation(s)	RIMS: STANDARD ALLOY RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
ont Tyre	225/45R17	PIRELLI	7
ont Tyre ont Tyre		PIRELLI PIRELLI	7 7
ont Tyre ar Tyre	225/45R17	+	7 7
ont Tyre	225/45R17 225/45R17	PIRELLI	7
ont Tyre ar Tyre ar Tyre	225/45R17 225/45R17 225/45R17 225/45R17 Description	PIRELLI PIRELLI PIRELLI	7 7
ont Tyre ar Tyre ar Tyre	225/45R17 225/45R17 225/45R17 225/45R17	PIRELLI PIRELLI PIRELLI	7 7
ont Tyre ar Tyre ar Tyre	225/45R17 225/45R17 225/45R17 225/45R17 Description PLETED ITS REPAIR WORKS.	PIRELLI PIRELLI PIRELLI	7 7
ont Tyre ar Tyre ar Tyre LE HAD COM	225/45R17 225/45R17 225/45R17 225/45R17 Description PLETED ITS REPAIR WORKS.	PIRELLI PIRELLI PIRELLI of Damages	7 7
ont Tyre ar Tyre ar Tyre LE HAD COM	225/45R17 225/45R17 225/45R17 225/45R17 Description PLETED ITS REPAIR WORKS. E DETAILS. General In	PIRELLI PIRELLI PIRELLI of Damages formation Inspection Date	7 7 7 7
ont Tyre ar Tyre ar Tyre LE HAD CON	225/45R17 225/45R17 225/45R17 225/45R17 Description PLETED ITS REPAIR WORKS. E DETAILS. General In	PIRELLI PIRELLI PIRELLI of Damages formation Inspection Date	7 7 7 7
ont Tyre ar Tyre ar Tyre LE HAD CON NDITION SE	225/45R17 225/45R17 225/45R17 225/45R17 Description PLETED ITS REPAIR WORKS. E DETAILS. General In 02/04/2024 833 MOTORSPORTS PTE LTD - 160	PIRELLI PIRELLI PIRELLI of Damages formation Inspection Date SIN MING DRIVE #	7 7 7 7
ont Tyre ar Tyre ar Tyre LE HAD COM NDITION SE nt Date held at	225/45R17 225/45R17 225/45R17 225/45R17 Description MPLETED ITS REPAIR WORKS. E DETAILS. General In 02/04/2024 833 MOTORSPORTS PTE LTD - 160 SINGAPORE 575722	PIRELLI PIRELLI PIRELLI Of Damages formation Inspection Date SIN MING DRIVE # arks EJUDICE" BASIS.	7 7 7 16/12/2024 02-09 AUTOCITY BUILDING
	AFFLES QUAPORE 04858 I Veh. No. From Model No. s No.	Policy Particulars:- THIRD PARTY Of Veh. No No. BVS24/0236 From PATRICK YONG Vehicle Model VOLKSWAGEN TOURAN (A) No. CAV245542 S No. WVGZZZ1TZBW043224 Ster 292065 KM IN ORDER Sation(s) RIMS: STANDARD ALLOY RIM Conditions	Y INSURANCE PTE LTD AFFLES QUAY #25-01 NORTH TOWER PORE 048583 Code: Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL Veh. SNL 2559M Veh. Inspected No Coverage No. BVS24/0236 Excess From PATRICK YONG Assign Date Vehicle Details Model VOLKSWAGEN TOURAN (A) C.C No. CAV245542 Year of Reg. S No. WVGZZZ1TZBW043224 Colour Oter 292065 KM Steering IN ORDER General Eation(s) RIMS: STANDARD ALLOY RIM Conditions of Tyres

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days