



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

|  |       |                       |
|--|-------|-----------------------|
| MS LONPAC INSURANCE BHD                  | Ref:  | CS/LPC24120136/Knh3e2 |
| 300 BEACH ROAD                           | Date: | 23/12/2024            |
| #17-04/07 THE CONCOURSE SINGAPORE 199555 | Code: | LPC2                  |

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                      |                |            |
|--------------|----------------------|----------------|------------|
| Insured Veh. | YP 7369K             | Veh. Inspected | SMG 6462U  |
| Policy No.   | -                    | Coverage       | 0          |
| Claim No.    | 24/24/24/VC05/030299 | Excess         | \$0.00     |
| Assign From  | GERALD POH           | Assign Date    | 10/12/2024 |

### 2. Vehicle Details

|                 |                          |              |               |
|-----------------|--------------------------|--------------|---------------|
| Make & Model    | HONDA HRV (A)            | C.C          | 1496          |
| Engine No.      | L15B5670966              | Year of Reg. | 27/12/2018    |
| Chassis No.     | JHMRU1810JX200968        | Colour       | METALLIC GREY |
| Odometer        | 106976 KM                | Steering     | IN ORDER      |
| Brakes          | IN ORDER                 | General      | GOOD          |
| Modification(s) | RIMS: STANDARD ALLOY RIM |              |               |

### 3. Conditions of Tyres

|                | Size      | Make        | Balance (mm) |
|----------------|-----------|-------------|--------------|
| R/H Front Tyre | 215/60R16 | CONTINENTAL | 9            |
| L/H Front Tyre | 215/60R16 | CONTINENTAL | 9            |
| R/H Rear Tyre  | 215/60R16 | CONTINENTAL | 9            |
| L/H Rear Tyre  | 215/60R16 | CONTINENTAL | 9            |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

|                |   |                 |            |
|----------------|---|-----------------|------------|
| Accident Date  | 08/12/2024  | Inspection Date | 10/12/2024 |
| Survey held at | READY AUTO CARE PL<br>BLK 10 #03-06, AMK AUTOPOINT, ANG MO KIO AVE 5, INDUSTRIAL PARK 2A, SINGAPORE<br>568047 |                 |            |

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days