

(08/11/13) . wef

ASS. REC. BY: Marcus

REF:

CS / Lip 24070011/unh3**ASSIGNMENT**

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: F3B 6P34Gat Workshop m/s Sanfu 12m

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

☒	☒
N/S	O/S
☒	☒

Bal. or Market Value: 85kIDAC Accident Rpt: _____ Consistent? : **Yes or No**GIA / PR Seen: _____ Consistent? : **Yes or No**Est. Repairs: 3 days Res.: **Yes or No**Lum Sum: 20 % 3 Val.: **Yes or No****CA / REV / REP. / 24 HRS**3353Vehicle: **IN / OUT**

Date: _____ Person Contacted: _____

Veh No: F3B6934GYr Regn: 22/06/07Type: **M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /**

Truck / Trailer or _____

Make: Kia X-1Rc.c 135Colour: BlueA/C: **Insured / Std / NI / NA**Sp.Reading: 0000T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: 453502221Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt or** okBrake: **Inorder / Jammed / Leaked / Burnt or**Modi: **Nil / STD A/Rim /**Tyre Size: **F:** _____**R:** 70-90-17**BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /****TOYO / YOKO or** Maxxis**Front****Rear**R/Bal. 6 mmR/Bal. 6 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 25/06/24D.O.I. 1/7/24

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**Rear & O/S Body**The U/C / Chassis frame / Body Structure affected due to collision.**

Date / Time

Action / Instruction

007/500Car not 31-03-2022 LTP 17/8Not 3282 like go other wkspSubmit report bike hasn't send in for repair

Date/Time, File Pass to?

☐: **Preli. Report**

1)

☐: **Final Report**

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)) S + RS \$ _____

) Photos _____

) Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	335J
Vehicle Details	
Vehicle No.:	FBB6934G
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Jun 2024
Vehicle Make:	YAMAHA
Vehicle Model:	X-1R
Primary Colour:	Blue
Manufacturing Year:	2007
Engine No.:	4S3502221
Chassis No.:	4S3502221
Maximum Power Output:	-
Open Market Value:	\$1,831.00
Original Registration Date:	22 Jun 2007
First Registration Date:	22 Jun 2007
Transfer Count:	8
Actual ARF Paid:	\$275.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Mar 2027
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$6,256.00
COE Rebate Amount:	\$1,728.00
Total Rebate Amount:	\$1,728.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 26 Jun 2024

OK



Bike model

Search

Type Of Vehicle

Any

Price From

Any

Price To

Any

Class

Any

More Search Options

Sort By

Recommended

RESERVED



Yamaha X1-R 135

Reg Date : 13/08/2010

Capacity : 135cc

Vehicle Type : Cubs

Mileage : -

SGD \$12800

Posted on : 11/06/2024

★ Paid Ad

★ Dealer Ad

Details >



Yamaha X1-R 135

Reg Date : 18/03/2008

Capacity : 135cc

Vehicle Type : Cubs

Mileage : -

SGD \$8800

Posted on : 21/06/2024

★ Paid Ad

★ Dealer Ad

Details >

first 1 last





ASSESSMENT FOR REPAIR : FBB6934G

YAMAHA X-1R

COE EXPIRY : 2027.03.31

not Authorized
 den 90096608
 1/7/24
 2/59
 telephone after repair
 3 days

Lump Sum

Part by Part

Qty Description

1	HANDLE BAR
1	RH - BRAKE PUMP (BREMBO) with level
1	RH - MIRROR
1	BAR END
1	RH - FRONT SIGNAL LIGHT
1	BRAKE PEDAL
1	RH - RIDER FOOTREST
1	RH - ENGINE COVER / CLUTCH COVER
1	RH - PILLION FOOTPEG
1	SPEEDOMETER FRONT COVER

Repairer's Estimate	1st Survey	Repair Survey	Final Survey
299.75	?		
970.10	cut ✓		
55.00	mis ✓		
72.00	cut ✓		
65.00	cut ✓		
55.00	cut/suf ✓		
55.00	cut ✓		
272.50	rx		
28.00	cut ✓		
85.00	cut ✓		

102
 1,957.35

Special Nett Items

STEERING CONE & BEARING
 FRONT FORK ALIGNMENT
 WHEEL ALIGNMENT
 FRAME ALIGNMENT
 PLASTIC COVER SET
 FULL SET COVER SET
 YOSHIMURA TRIOVAL

130.00	1 rx		
230.00	1 rx		
130.00	1 rx		
210.00	1 rx		
348.80	cut ✓		
763.00	cut ✓		
1,853.00	cut ✓		

1300

3,664.80

Total Parts

5,622.15

Labour Charges

1	Workmanship to renew damage parts & areas
	\$100 per days X 4 days

400.00 250
 400.00

Total Parts & Labours Concluded

6,022.15

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts, before repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be reassembled and is subject to final approval from Insurance Company

SANFU MOTOR PTE LTD: acknowledged by Repairer

Company Reg No.: 200612487G re:

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com