

REF:

ASSIGNMENT

From: _____ Date: _____

Estim: ~~Est~~ ^{Est}OD / ~~IP~~ / TP RES / OD RES / EVA / INV / MVTo In ~~Est~~ ^{Est} Vehicle No: _____at Work ~~Shop~~ ^{Shop} _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNRS296UYr Regn: 2016 / NovType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi Q5 C.D. 1984Colour: White A/C: Insured / Std / NI / NASp. Reading: 83267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAUZZ28R9H4019475Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / B/Rim / STD A/Rim orTyre Size: F: 255/50R19R: 255/50R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/02/24Survey held at One Garage

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front n/s, u/c -

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>1P Great American</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes ()</u>
	<u>1st Survey : No ()</u>
	<u>MV : 56K</u>
	<u>PV : 34.5K</u>
	<u>Nett : 21.5K</u>
	<u>964F.</u>

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

2)

Add Fee:

☐

Site Insp (\$

Interview (\$

Tech. Inve (\$

Survey Fee:

Transportation:

S + RS \$1

Photos

Others

Report Formed:

Report Formed:

BOX TYRES PTE LTD
8 KAKI BUKIT AVE.4
#02-40 S(417875)

Customer

Vehicle ident no.
SNR5296U

Repair order no.
R017028

Technician
ONE GARAGE

Date
9.12.24

License plate no. First reg. date Model Odometer reading: km/miles
Audi : Q5/SQ5 Quattro : 2008-17 (8R) : Standard 1
Suspension (1BA) 2013-

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-1°20' +/-0°25'	-1°47'
		right			-1°59'
		cross		0°00' +/-0°30'	0°12'
	Toe	left		0°10' +/-0°05'	0°05'
		right			0°06'
		total		0°20' +/-0°10'	0°11'
	Geometrical driving axis			0°00' +/-0°10'	0°00'
Front axle	Camber	left		-0°24' +/-0°23'	-2°16'
		right			-0°53'
		cross		0°00' +/-0°30'	-1°23'
	Caster	left			
		right			
		cross			0°00'
	SAI	left			
		right			
		cross			0°00'
	Track differential angle	left		-1°49' +/-0°30'	
		right			
	Toe	left		0°10' +/-0°05'	-1°47'
		right			0°03'
		total		0°20' +/-0°10'	-1°44'
	Setback			0°00'	
	Max steering lock	left steer	left	-39°54' +1°30' -2°00'	
		left steer	right	33°30' +1°30' -2°00'	
		right steer	left	33°30' +1°30' -2°00'	
		right steer	right	-39°54' +1°30' -2°00'	