

CS/AGI24120137/Aqh3

ASSIGNMENT

From: _____ Date: _____
 Estn: 22/01/01
 OD / IP/RS / TP RES / OD RES / EVA / INV / MV
 To In Vehicle No: _____
 at Work Shop / _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)

Veh No: SNRS296U Yr Regn: 2016 / Nov
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Audi Q5 C.D. 1984
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 83267 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZ8R9H4019475
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or _____
 Brake: Order / Jammed / Leaked / Burnt or _____
 Mod: Nil / B/Rim / STD A/Rim or _____
 Tyre Size: F: 255/50R19
 R: 255/50R19

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 6 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 16/02/24
 Survey held at One Garage
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Front n/s, u/c -
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>1P Great American</u> COE Expiry: _____
	<u>LS \$9600, 6 days (Red \$19522.45, 67%)</u>
	<u>MV: 56K</u> Estimate given during: Yes () 1st Survey No ()
	<u>PV: 34.5K</u>
	<u>Nett: 21.5K</u>
	<u>964F.</u>

Date/Time, File Pass to? ☐ : Preli. Report
 1) 17/01 Typist ☐ : Final Report
 Date/Time, File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

3 + RS \$1

Photos

Others

Report Form: TP

Report Form: TP

BOX TYRES PTE LTD
8 KAKI BUKIT AVE.4
#02-40 S(417875)

Customer

Vehicle ident no.
SNR5296U

Repair order no.
R017028

Technician
ONE GARAGE

Date
9.12.24

License plate no.

First reg. date

Model

Odometer reading: km/miles

Audi : Q5/SQ5 Quattro : 2008-17 (8R) : Standard
Suspension (1BA) 2013-

1

Complaints or reason for alignment check

			Before	Target Data	Actual
Rear axle	Camber	left		-1°20' +/-0°25'	-1°47'
		right			-1°59'
		cross		0°00' +/-0°30'	0°12'
	Toe	left		0°10' +/-0°05'	0°05'
		right			0°06'
		total		0°20' +/-0°10'	0°11'
	Geometrical driving axis			0°00' +/-0°10'	0°00'
Front axle	Camber	left		-0°24' +/-0°23'	-2°16'
		right			-0°53'
		cross		0°00' +/-0°30'	-1°23'
	Caster	left			
		right			
		cross		0°00'	
	SAI	left			
		right			
		cross		0°00'	
	Track differential angle	left		-1°49' +/-0°30'	
		right			
	Toe	left		0°10' +/-0°05'	-1°47'
		right			0°03'
		total		0°20' +/-0°10'	-1°44'
	Setback			0°00'	
	Max steering lock	left steer	left	-39°54' +1°30' -2°00'	
		right steer	right	33°30' +1°30' -2°00'	
			left	33°30' +1°30' -2°00'	
		right	right	-39°54' +1°30' -2°00'	