

ASS. REC. BY:

REF: FC21 CS/FCI24120139/Kvh3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

SHC 564D

Policy No.

Claims No.

D24010727MFCT

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8180/c

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1.B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

WD 7358D

Yr Regn:

12, 23

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

CAMC

HN5311X c.c.

11813

Colour

White / Blue

A/C: Insured / Std / NI / NA

Sp. Reading

29247

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

175N20E 58PB 004437

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: M / S / Rim / STD A / Rim or

Tyre Size:

Wonde / 315 / 80R22.5R: Accler

BS / DUN / EXNOVA / GY / FS / LIZA / MICTORTSU / PIR / SUMI / CDI

TOYO / YOKO or

Front

R/Bal.

4 5 mm

Rear

R/Bal.

66 55 mm

L/Bal.

4 5 mm

L/Bal.

66 55 mm

D.O.A.

6/12/24

D.O.I.

11/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

11/128 Foot Cahn

(red 10,012.60, 93%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	841G

Vehicle Details

Vehicle No.:	WD7358D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	09 Dec 2024
Vehicle Make:	CAMC
Vehicle Model:	HN5311X40D9M6
Primary Colour:	White
Secondary Colour:	Blue
Manufacturing Year:	2023
Engine No.:	CM6D2840060123J03163
Chassis No.:	LZ5N2DE58PB004437
Maximum Power Output:	-
Open Market Value:	\$95,101.00
Original Registration Date:	04 Dec 2023
First Registration Date:	04 Dec 2023
Transfer Count:	0
Actual ARF Paid:	\$4,756.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	03 Dec 2033
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$73,889.00
COE Rebate Amount:	\$59,111.00
Total Rebate Amount:	\$59,111.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 09 Dec 2024

OK

HANDPHONE 90030857

Date : 11 Dec 2024

QUOTATION - THIRD PARTY CLAIM

FIRST CAPITAL

DATE ACCIDENT : 6 Dec 2024

ATTN : MOTOR CLAIM DEPARTMENT

CLAIM : THIRD PARTY CLAIM

VEH. No WD 7358

INSURE : INCOME INSURANCE

QTY	ITEM	AMOUNT	
1	FRONT BUMPER	\$ R 2,985.00	X
1	HEADLAMP RH	\$ Sn 1,485.00	X
1	SIGNAL LAMP RH	\$ Sn 859.00	X
1	FRONT BUMPER OUTER NET / COVER	\$ Rd 580.00	✓ 20052
1	STEP PANEL HOUSING RH	\$ Sn 850.00	X
1	STEP PANEL TOP RH	\$ Sn 335.00	X
1	STEP PANEL CENTER RH	\$ n 335.00	X
1	STEP PANEL BOTTOM RH	\$ n 335.00	X
1	STEP PANEL LOWER SUPPORT RH	\$ n 1,650.00	X
TOTAL PARTS :		\$ 9,414.00	
LESS 10%		\$ 941.40	
TOTAL LIST PARTS :		\$ 8,472.60	
TOTAL PARTS PRICE :		\$ 8,472.60	

AMOUNT BRING FORWARD :

\$ 8,472.60

Labour charges

\$ 1,000.00

3001

To do anti rust

\$ n 120.00

X

To check wiring system

\$ n 120.00

X

To do spray painting on accident affected area

\$ 1,000.00

200

TOTAL LABOUR :

\$ 2,240.00

GRAND TOTAL PARTS AND LABOUR :

\$

10,712.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: