

ASS. REC. BY:

REF: 17021Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s SQMof 8416

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$180k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 02 days Res.: Yes or NoLum Sum: 1.8.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: WD 7358D Yr Regn: 12, 23

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Concrete MixerMake: CAMC HN5311X c.c. 11813Colour: White / Blue A/C: Insured / Std / NI / NASp. Reading: 29297 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 175N20E 58PB 004437

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Mil / S/Rim / STD A/Rim orTyre Size: F: Wanda / 315 / 80R22.5R/A colour: Academy CDBS / DUN / EXNOVA / GS / FS / LIZA / MICTORTSU / PIR / SUMI / CD

TOYO / YOKO or

Front

Rear

R/Bal. 4 5mmR/Bal. 66 55mmL/Bal. 4 5mmL/Bal. 88 55mmD.O.A. 6/12/24D.O.I. 11/12/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: _____

1) ☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

Add Fee: ☐ : Site Insp (\$

Transportation

☐ : Interview (\$

S + RS. SI

☐ : Tech Invs (\$

F. P. S.

☐ : Weekend (\$

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Date : 11 Dec 2024

QUOTATION - THIRD PARTY CLAIM

FIRST CAPITAL

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 6 Dec 2024

VEH. No WD 7358

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INCOME INSURANCE

QTY	ITEM	AMOUNT	
1	FRONT BUMPER	\$ R 2,985.00	X
1	HEADLAMP RH	\$ Sn 1,485.00	X
1	SIGNAL LAMP RH	\$ Sn 859.00	X
1	FRONT BUMPER OUTER NET / COVER	\$ Rd 580.00	✓
1	STEP PANEL HOUSING RH	\$ Sn 850.00	X
1	STEP PANEL TOP RH	\$ Sn 335.00	X
1	STEP PANEL CENTER RH	\$ R 335.00	X
1	STEP PANEL BOTTOM RH	\$ R 335.00	X
1	STEP PANEL LOWER SUPPORT RH	\$ R 1,650.00	X
TOTAL PARTS :		\$ 9,414.00	
LESS 10%		\$ 941.40	
TOTAL LIST PARTS :		\$ 8,472.60	
TOTAL PARTS PRICE :		\$ 8,472.60	

AMOUNT BRING FORWARD :

\$ 8,472.60

Labour charges

\$ 1,000.00

300/

To do anti rust

\$ Sn 120.00

X

To check wiring system

\$ Sn 120.00

X

To do spray painting on accident affected area

\$ 1,000.00

200/

TOTAL LABOUR :

\$ 2,240.00

GRAND TOTAL PARTS AND LABOUR :

\$

10,712.60

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: