

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	NCE LTD		Ref:	CS/INC24120140/Uqh3e2(N)	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557		Date:	02/01/2025	
	ATTN: EILEEN LEI	E		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFG 6888H	Veh. Inspected		SMF 5595G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1307580-002	Excess (\$)		0.00	
	Assign From		Assign Date		10/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	MAZDA 3 (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JM6BN22A8K0248910	Colour		GREY	
	Odometer	181381 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55Z R16	VIENTO		5 mm	
	L/H Front Tyre	205/55Z R16	VIENTO		5 mm	
	R/H Rear Tyre	205/55Z R16	VIENTO		5 mm	
	L/H Rear Tyre	205/55Z R16	VIENTO		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	07/12/2024	Inspect Date / T	Γime	10/12/2024 (01:24 PM)	
	Survey held at	LEANG AUTOMOTIVE				
		BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
	•					