



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN LEE

Ref: CS/INC24120142/Anh3m4(N)

Date: 18/06/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMV 1340S	Veh. Inspected	SLV 1752Z
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1307728-001	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	10/12/2024

2. Vehicle Particulars & Condition

Make & Model	BMW 116D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WBA1V72020V945303	Colour	WHITE
Odometer	141797 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/40R18	MICHELIN	6 mm
L/H Front Tyre	225/40R18	MICHELIN	6 mm
R/H Rear Tyre	225/40R18	MICHELIN	6 mm
L/H Rear Tyre	225/40R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/12/2024	Inspect Date / Time	17/12/2024 (03:24 PM)
Survey held at	ADVANCE AUTO GARAGE 1 KAKI BUKIT AVENUE 6, #01-73 KAKI BUKIT AUTOBAY BLK D, SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**