Name Unknown Gender Female PASSENGER 7 Name Unknown Gender Female DETAILS OF POLICE ACTION Was the accident reported to the police? Police Station Name Ang Mo Kio South Neighbourhood Police Centre Police Station Phone No (Phone) +65-18004519999 Alt. Police Station Phone No (Fax) +65-65535679 Police Station Address 81 Ang Mo Kio Ave 3 Singapore 569929

Nο

CIRCUMSTANCES OF ACCIDENT

On the above-mentioned date, time and location. I was driving my bus service 166 at upper Thomson Road. I then stopped my vehicle at the bus stop (53029) and immediately after stopping, the other party (Bus svc 980) hit unto the rear of my vehicle. For both of our buses, I was informed by my company that 1 1 people were injured. I myself was injured and was escorted by ambulance to Tan Tock Seng Hospital and was given 3 days of MC. Traffic police also came down to scene for this case. I was then advised by my company to lodge a police report regarding this issue.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

Was notice of intended Prosecution given?

If yes, against whom?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMB1361L Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Bus Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident Front portion damaged No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person Lim Yew Chong (Lin Youzhong) Gender Male Phone No Address Address Complement Post Code Approximate Age Years Old Injuries Sustained left Forehead slightly bleeding and both Elbows swollen Injured person in which vehicle? SBS5062P Were seat belts worn? Was this injured conveyed to hospital by ambulance? Yes