ASS, REC. BY:

Steve

REF:

CS/INC24120157/Eqh3

ASSIGNMENT

rom: Date:	Veh No: SNR7475G Yr Regn: 01 Jul 2024
-stimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: HYUNDAI SX2 KONA c.c 1580
at Workshop m/s	Colour Black A/C: Insured / Std / NI / NA
	Sp.Reading 49006 T/Radio: Insured / Std / NI / NA
of	Eng/No:
Policy No.	C/No: KMHHB811VRU070998
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205/65R16
(Policy Condition)	R:
Remark: The veh had commenced its	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM! /
repair at the time of inspection.	TOYO / YOKO or KUMHO
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 3 mm R/Bal. 3 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 3 mm L/Bal. 3 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 05/12/24 D.O.I. 11/12/24
Lum Sum: % 3 Val.: Yes or No	Survey held at TWINCAR AUTOMOTIVE
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV - \$150k	
PV - \$106,451.00	
NV - \$43,549.00	
	<u>.</u>
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	ee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Rep Formai:	: Tech. Invs (\$) Others
Lump Sum / LBJ: (F	:Weelfend (\$)
	TOTAL
9 8	