

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	MS FIRST CAPITA	L INSURANCE LTD	R	tef:	CS/FCI24120165/Evh3m4(N)	
	16 RAFFLES QUA' #42-01 HONG LEC 048581	Y NG BUILDINGSINGAPORE	D	ate:	09/01/2025	
	ATTN: KAREN TAN	N	C	ode:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SHA 9136H	Veh. Inspected		ED 9770X	
	Policy No.	D-24101860MFCT	Coverage (\$)		0.00	
	Claim No.	D24010764MFCT	Excess (\$)		0.00	
	Assign From	EILEEN WANG	Assign Date		11/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VOXY	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2023	
	Chassis No.	ZWR900103287	Colour		BLACK	
	Odometer	108581 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	205/55 R17	MICHELIN		5 mm	
	L/H Front Tyre	205/55 R17	MICHELIN		5 mm	
	R/H Rear Tyre	205/55 R17	MICHELIN		5 mm	
	L/H Rear Tyre	205/55 R17	MICHELIN		5 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/12/2024	Inspection Date		12/12/2024	
	Survey held at	TICK HAI MOTOR & WELDING SERVICES				
		BLK 1 KAKI BUKIT AVE 6 #01-54 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days					