

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP / RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W TP / s _____
 of _____
 Insured: _____
 Policy No: _____
 Claim's No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vch: _____
 (Policy Condition)

N/S	O/S

Remarks: There had commenced its repair at the time of inspection.

Bel. or Market Value: _____
 IDAC Accident Report _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SNN9691G Yr Regn: 2017, Feb.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Honda Civic C.D. 1498
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 117698 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHFC1660GT000492
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/40 R18
 R: 225/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front Rear
 R/Bal. ob mm R/Bal. ob mm
 L/Bal. ob mm L/Bal. ob mm
 D.O.A. _____ D.O.I. 02/12/24
 Survey held at JL Perfect

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP Check</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV : 431K</u>
	<u>PV : 27.2K</u>
	<u>Nett : 15.8K</u>
	<u>585H</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

1)

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

Report Format:

Report Form: F.P.P. P. C.

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 29.11.2024

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SNN9691G
MODEL : HONDA CIVIC
DATE OF ACCIDENT : 28.11.2024
TIME OF ACCIDENT : 17:20 HOURS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER FOGLAMP RH <i>new</i>	1	\$ 273.30	\$ 273.30
2	FRONT BUMPER FOGLAMP COVER GARNISH RH <i>new</i>	1	\$ 43.10	\$ 43.10
3	FRONT BUMPER RETAINER <i>new</i>	2	\$ 33.60	\$ 67.20
4	FRONT DOOR SIDE MIRROR RH <i>new</i>	1	\$ 596.80	\$ 596.80
5	FRONT FENDER RH <i>Beats Perfed</i>	1	\$ 480.40	\$ 480.40
6	FRONT FENDER SIGNAL LAMP RH <i>lit</i>	1	\$ 49.60	\$ 49.60
7	FRONT FENDER COWLING RH <i>born</i>	1	\$ 132.10	\$ 132.10
8	HEADLAMP (LED) RH <i>Combined</i>	1	\$ 894.90 <i>1551.80</i>	\$ 894.90 <i>1551.80</i>
9	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 48.30	\$ 48.30
10	HEADLAMP TOP MOULDING (BLACK) RH <i>new</i>	1	\$ 144.20	\$ 144.20
11	WIPER TANK <i>new</i>	1	\$ 169.10	\$ 169.10
12	FRONT GRILLE <i>new</i>	1	\$ 171.20	\$ 171.20
13	FRONT GRILLE LOGO <i>new</i>	1	\$ 38.40	\$ 38.40
14	FRONT GRILLE CHROME <i>new</i>	1	\$ 130.40	\$ 130.40
15	FRONT WHEEL SPORT RIM RH <i>lit</i>	1	\$ 769.20	\$ 769.20
16	FRONT ABS SENSOR RH <i>new</i>	1	\$ 149.20	\$ 149.20
17	FRONT SHOCK ABSORBER RH <i>new</i>	1	\$ 368.20	\$ 368.20
18	FRONT KNUCK ARM RH	1	\$ 284.40	\$ 284.40
19	FRONT LOWER ARM RH	1	\$ 439.30	\$ 439.30
20	FRONT WHEEL HUP WITH BEARING RH	1	\$ 263.70	\$ 263.70
21	FRONT LINKAGE RH <i>new</i>	1	\$ 186.50	\$ 186.50
22	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 1,976.10	\$ 1,976.10

TO : CHINA TAIHING MOTOR CLAIMS DEPTS
 VEHICLE NO : SNN9691G
 MODEL : HONDA CIVIC
 DATE OF ACCIDENT : 28.11.2024
 TIME OF ACCIDENT : 17:20 HOURS

TOTAL PRICE \$ 7,675.60
 LESS 20% \$ 1,535.12
 SUB TOTAL PRICE \$ 6,140.48

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
2	FRONT BUMPER FOGLAMP COVER GARNISH CLIP RH (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
3	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
4	FRONT GRILLE CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	FRONT SIDE MIRROR COVER (CARBON FIBER) <i>new</i>	1	\$ 800.00	\$ 800.00
7	FRONT BUMPER (TYPR R) (SPECAIL TYPE) <i>Rehd</i>	1	\$ 2,500.00	\$ 2,500.00
8	FRONT BUMPER LOWER LID (CARBON FIBER) <i>fit</i>	1	\$ 1,800.00	\$ 1,800.00
9	FRONT WHEEL SPORT RIM RH <i>fit</i>	1	\$ 1,800.00	\$ 1,800.00
10	FRONT WHEEL TYRE RH <i>new</i>	1	\$ 800.00	\$ 800.00
11	WHEEL CAP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
12	BRAKE OIL <i>new</i>	1	\$ 1,210.00	\$ 1,210.00

TOTAL \$ 8,140.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,000.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	400
3	WIRING CHECK	\$ 250.00	30
4	REMOVE AND REFIX FRONT UNDERCARRIAGE RH	\$ 650.00	?
5	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	X
6	TO PRESS FRONT WHEEL BEARING	\$ 80.00	X
7	REFOCUS HEADLAMP BEAM	\$ 80.00	X

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SNN9691G
MODEL : HONDA CIVIC
DATE OF ACCIDENT : 28.11.2024
TIME OF ACCIDENT : 17:20 HOURS

8	FOUR WHEEL ALIGNMNET	\$ 120.00	80
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 3,710.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 14,280.48
TOTAL LABOUR COST : \$ 3,710.00
TOTAL REPAIR COST : \$ 17,990.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian
L/S 02/12/24
05 days