

ASS. REC. BY: Taujiah

REF: CS/CT124126170/1743

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. SNM24D206789

Sum Insured: _____ Excess: \$2500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

XXX	
N/S	O/S

Bal. or Market Value: \$300K

IDAC Accident Rpt _____ Consistent? : Yes or No

GIA / PR Seent _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: Eric

Vehicle: IN / OUT

Veh No: SKJ1000K Yr Regn: 2020/03

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Cayenne E3 c.c. 2995

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 109591 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WP1ZZZ9Y-ZLDA03380

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modl: Nil / SRim / STD A/Rim or

Tyre Size: F: 285/40R21

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 30/11/2024 D.O.I. 17/12/24

Survey held at Trans Eurokar

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/2/25	Final fig \$50,512.70 confirmed by email (Red 13,227.00, 20%)

Date/Time, File Pass to? ☐ : Prell. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 14

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Insp (\$ _____)

Survey Fee:

Transportation:

☐ S + RS ☐ SI

Photos

Others

QUOTATION

CODE: C0011
 CUSTOMER: CHINA TAIPING INSURANCE (SINGAPORE)
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366
 MODEL: PORSCHE - CAYENNE
 CHASSIS NO.: WP1ZZZ9YLDA03380
 ENGINE NO.: 201632
 REG NO.: SKJ1000K
 REGN DATE: 24/03/2020

PAGE NO.: 1
 DOCUMENT NO.: 786
 DOCUMENT DATE: 11/12/2024
 POS ID: ES
 PRINTED BY: Muhammad Nur Faiz
 SERVICE ADV: Muhammad Nur Faiz
 CSP/OP CODE: W
 DEPT: 32084
 WIP NO.: DS/SKJ1000K/0371
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	OWN DAMAGE CLAIM - CHINA TAIPING	0.00	0.00		0.00	O
INS-PB-(L)	TO REMOVE /REPLACE BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT SUPPORT PANEL & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR FRONT DOOR LH & ALL AREAS AFFECTED BY THE ACCIDENT.	13,760.00	1.00	10320	13,760.00	S
INS-PAINT-(L)	TO RESPRAY BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH.	5,300.00	1.00	3800	5,300.00	S
INS-PB-(L)	TO CARRY-OUT BODY CAVITY PRESERVATION.	250.00	1.00	150	250.00	S
INS-PB-(L)	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET.	150.00	1.00	✓	150.00	S
INS-PB-(L)	TO REMOVE & REPLACE TURBO COOLER & REFIT RADIATOR, CONDENSER AND RADIATOR FAN ASSY.	1,720.00	1.00	✓	1,720.00	S
INS-PB-(L)	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	500.00	1.00	✓	500.00	S
INS-PB-(L)	TO TRANSFER THE FRONT SENSORS.	500.00	1.00	250	500.00	S
INS-PB-(L)	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	250.00	1.00	150	250.00	S
INS-PB-(L)	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	600.00	1.00	✓	600.00	S
INS-PB-(L)	TO TOW THE VEHICLE FROM THE ACCIDENT SITE TO THE WORKSHOP.	300.00	1.00	? 250	300.00	S

total invoice

Tanjong 97195749/62563561
 Not Authorise Ex \$2500
 10-11 days
 17/12/24 E Ham
 P/P Resurvey before paint tanjong e (khanh.com)

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

QUOTATION

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPORE)
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366
MODEL: PORSCHE - CAYENNE
CHASSIS NO.: WP1ZZZ9YZLDA03380
ENGINE NO.: 201632
REG NO.: SKJ1000K
REGN DATE: 24/03/2020

PAGE NO.: 2
DOCUMENT NO.: 786
DOCUMENT DATE: 11/12/2024
POS ID: ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV: Muhammad Nur Faiz
CSP/OP CODE: W
DEPT: 32084
REF. NO.: DS/SKJ1000K/0371
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
INS-PB-(L)	SUNDRIES.	50.00	1.00		50.00	S
9Y0-807-217- -G2X	FRONT BUMPER	1.00	2,888.50	de	2,888.50	S
WHT-004-935- -	Expander nut	4.00	2.00	nei	8.00	S
9Y0-423-337- -	Clamp	4.00	5.80	nei	23.20	S
N -038-501-2 -	Spreader rivet	8.00	2.10	nei	16.80	S
9Y0-807-685- -OK1	GRILLE TRIM LH	1.00	188.40	de	188.40	S
9Y0-807-877- -OK1	Disc LH CENTER	1.00	131.30	de	131.30	S
9Y0-807-973- -OK1	Disc LH LOWER	1.00	123.80	de	123.80	S
9Y0-807-245- -M7U	DISC TRIM LH UPPER	1.00	159.50	de	159.50	S
9Y0-807-245-A -M7U	DISC TRIM LOWER LH	1.00	159.50	de	159.50	S
9Y0-807-061- -OK1	FRONT BUMPER LOWER SPOILER	1.00	1,224.00	de	1,224.00	S
9Y0-807-833- -6M7	Cover Brushed stainless stel	1.00	1,211.30	X	1,211.30	S
9Y0-807-684- -OK1	GRILLE CENTER LOWER	1.00	216.90	de	216.90	S
9Y0-807-683-P -OK1	FRONT GRILLE CENTER UPPER	1.00	416.00	de	416.00	S
9Y0-807-681- -OK1	FRONT GRILLE LH	1.00	227.60	de	227.60	S
9Y0-807-675- -OK1	GRILLE LOWER LH	1.00	160.80	de	160.80	S
9Y0-423-337- -	Clamp	4.00	5.80	nei	23.20	S
9Y0-807-161- -	AIR DUCT GRILLE LH INNER	1.00	180.30	de	180.30	S
9Y0-807-177-C -	BUMPER GUIDE LH	1.00	115.00	de	115.00	S
WHT-004-935- -	Expander nut	6.00	2.00	nei	12.00	S

This is only an estimate from our visual inspection and should there be more damages found during process of works you will then be informed for your approval before proceeding with the repairs.

We note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

Our estimate is valid for a period of thirty (30) days only.

Prices are subject to change without prior notice.

QUOTATION

CODE: C0011
 CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO)
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366
 MODEL: PORSCHE - CAYENNE
 CHASSIS NO.: WP1ZZZ9YZLDA03380
 ENGINE NO.: 201632
 REG NO.: SKJ1000K
 REGN DATE: 24/03/2020

PAGE NO.: 3
 DOCUMENT NO.: 786
 DOCUMENT DATE: 11/12/2024
 POS ID: ES
 PRINTED BY: Muhammad Nur Faiz
 SERVICE ADV: Muhammad Nur Faiz
 CSP/OP CODE: W
 DEPT: 32084
 WIP NO.: DS/SKJ1000K/0371
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
N -903-463-01-	Blind rivet	10.00	2.10	all	21.00	S
9Y0-807-957-C -OK1	AIR GUIDE SIDE LH	1.00	90.50	?	90.50	S
9Y0-807-959- -OK1	AIR GUIDE LOWER LH	1.00	65.90	?	65.90	S
9Y0-807-665- -	FOAM PART UPPER LH	1.00	114.20	all	114.20	S
5Q0-919-133- -9B9	SENSOR GASKET	6.00	3.90	all	23.40	S
5Q0-919-275-C -G2X	SENSOR OUTER	1.00	382.70	?	382.70	S
9Y0-807-129- -	SENSOR BRACKET OUTER LH	1.00	48.90	all	48.90	S
9Y0-807-130- -	SENSOR BRACKET OUTER RH	1.00	48.90	all	48.90	S
5Q0-919-275-B -G2X	SENSOR INNER	1.00	319.80	?	319.80	S
9Y0-807-131- -	SENSOR BRACKET CENTER LH	1.00	48.90	all	48.90	S
9Y0-807-132- -	SENSOR BRACKET CENTER RH	1.00	48.90	all	48.90	S
9Y0-807-571-B -	HEADLIGHT BRACKET LH	1.00	92.00	all	92.00	S
9Y0-807-049-F -	BUMPER RETAINER RH	1.00	99.70	X	99.70	S
9Y0-805-015-C -	CARRIER UPPER	1.00	654.10	?	654.10	S
9Y0-805-241-B -	CROSS MEMBER UPPER	1.00	202.80	?	202.80	S
9Y0-129-251-D -	AIRDUCT UPPER FRT CENTER	1.00	167.10	?	167.10	S
9Y0-121-673- -	AIR DUCT REAR CENTER UPPER	1.00	211.40	?	211.40	S
9Y0-121-707-B -	AIR DUCT REAR CENTER	1.00	170.50	?	170.50	S
9Y0-121-699-C -OK1	AIR GUIDE CENTER LH	1.00	147.40	?	147.40	S
9Y0-121-710- -OK1	AIR GUIDE CENTER RH	1.00	151.70	X	151.70	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

QUOTATION

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO)
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIM DEPT

CONTACT NO.: 2222366
MODEL: PORSCHE - CAYENNE
CHASSIS NO.: WP1ZZZ9YZLDA03380
ENGINE NO.: 201632
REG NO.: SKJ1000K
REGN DATE: 24/03/2020

PAGE NO.: 4
DOCUMENT NO.: 786
DOCUMENT DATE: 11/12/2024
POS ID: ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV: Muhammad Nur Faiz
CSP/OP CODE: W
DEPT: 32084
WIP NO.: DS/SKJ1000K/0371
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross GST	
					amount	Code
			SGD		SGD	
9Y0-121-293- -	AIR DUCT CENTER LOWER	1.00	167.80	?	167.80	S
9Y0-805-519-F -OK1	VANES FLAP	1.00	850.10	X	850.10	S
9Y0-121-451-H -OK1	VANES FLAP CENTER LOWER	1.00	348.80	X	348.80	S
95B-965-501-AA-	MOTOR FOR VANES FLAP	1.00	455.00	de	455.00	S
9Y0-117-335-AC-OK	AIR GUIDE INTERCOOLER RH LH	1.00	255.10	cur	255.10	S
9Y0-122-355-E -OK1	AIR FLAP INTERCOOLER LH	1.00	300.00	de	300.00	S
95B-965-501-AB-	Servomotor	1.00	455.00	an	455.00	S
9A7-820-535- -	External temperature sensor	1.00	100.60	?	100.60	S
9Y0-805-594-R -	FRONT SUPPORT PANEL	1.00	1,046.60	cur	1,046.60	S
PAB-806-185- -	SLIDE RAIL LH	1.00	67.60	?	67.60	S
PAB-801-677-00-	Bracket SUPPORT LH	1.00	59.00	?	59.00	S
9Y0-807-109-B -	BUMPER REINFORCEMENT	1.00	1,561.10	?	1,561.10	S
N -908-173-02-	BLIND RIVET	6.00	3.50	an	21.00	S
9Y0-807-711-C -	BUMPER SUPPORT LH	1.00	64.30	?	64.30	S
9Y0-807-550-F -	FRONT BUMPER SPONGE	1.00	86.60	?	86.60	S
9Y0-805-515-C -	Bracket LH	1.00	117.20	?	117.20	S
9Y0-805-527-C -	Brace LH	1.00	76.50	?	76.50	S
PAB-802-037- -	Side member LH	1.00	426.20	?	426.20	S
PAB-802-441- -	Reinforcement LH	1.00	339.70	?	339.70	S
PAB-803-329- -	Support MEMBER LH	1.00	260.30	?	260.30	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

QUOTATION

CODE: C0011
 CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO)
 ADDRESS: 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 ATTN: MOTOR CLAIM DEPT

PAGE NO.: 5
 DOCUMENT NO.: 786
 DOCUMENT DATE: 11/12/2024
 POS ID: ES
 PRINTED BY: Muhammad Nur Faiz
 SERVICE ADV: Muhammad Nur Faiz
 CSP/OP CODE: W
 DEPT: 32084
 WIP NO.: DS/SKJ1000K/0371
 REF. NO.:
 DATE IN:
 EXT. WTY:
 MILEAGE: 0

CONTACT NO.: 2222366
 MODEL: PORSCHE - CAYENNE
 CHASSIS NO.: WP1ZZZ9YZLDA03380
 ENGINE NO.: 201632
 REG NO.: SKJ1000K
 REGN DATE: 24/03/2020

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
PAB-805-201- -	Bracket LOWER LH	1.00	83.40	?	83.40	S
9Y0-823-031-FY-GR	BONNET	1.00	4,762.20	bt	4,762.20	S
9Y0-823-301-E -	Hinge LH	1.00	139.30	?	139.30	S
9Y0-823-302-E -	Hinge RH	1.00	139.30	?	139.30	S
9Y0-823-359-A -	Damper	2.00	56.70	X	113.40	S
9Y0-823-187-B -	HINGE COVER LH	1.00	27.80	X	27.80	S
9Y0-823-185-A -	BONNET LOCK CATCH LH	1.00	104.20	X	104.20	S
9Y0-823-509-A -	BONNET LOCK	2.00	310.80	X	621.60	S
9Y0-863-831-B -	BONNET INSULATOR	1.00	314.70	X	314.70	S
1T0-863-727- -	INSULATOR CLIPS	12.00	1.20	nei	14.40	S
9Y0-805-504-F -OK1	SUPPORT LOCK TOP COVER	1.00	247.70	nei	247.70	S
9Y0-806-441-F -OK1	FENDER TOP COVER LH	1.00	194.10	nei	194.10	S
958-805-163-00-	Clip	3.00	6.00	nei	18.00	S
PAF-004-750- -	Spreader rivet	2.00	3.30	nei	6.60	S
9Y0-821-169-B -	Plenum chamber cover LH	1.00	147.40	?	147.40	S
9P1-853-601- -	PORSCHE CREST	1.00	356.50	nei	356.50	S
9P1-853-611- -	DESK PAD CREST	1.00	21.30	nei	21.30	S
WHT-004-974- -	Nut	2.00	2.30	nei	4.60	S
9Y0-821-105-DY-GR	FRONT FENDER LH	1.00	1,859.60	bt	1,859.60	S
PAB-821-131- -GRV	FENDER BRACE LH	1.00	179.60	?	179.60	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

QUOTATION

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPORE)
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIM DEPT

PAGE NO.: 6
DOCUMENT NO.: 786
DOCUMENT DATE: 11/12/2024
POS ID: ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV: Muhammad Nur Faiz
CSP/OP CODE: W
DEPT: 32084
WIP NO.: DS/SKJ1000K/0371
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 2222366
MODEL: PORSCHE - CAYENNE
CHASSIS NO.: WP1ZZZ9YLDA03380
ENGINE NO.: 201632
REG NO.: SKJ1000K
REGN DATE: 24/03/2020

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
9Y0-821-157-A -	FENDER STRUT LH	1.00	49.20	bt	49.20	S
958-821-431-00-GRV	FENDER BRACKET LH	1.00	97.40	bt	97.40	S
958-821-167-01-GRV	FENDER BRACKET REAR LH	1.00	79.90	X	79.90	S
9Y0-854-777-A -OK1	TRIM A-PILLAR RH	1.00	125.40	?	125.40	S
N -908-173-02-	rivetted cap nut	8.00	3.50	?	28.00	S
N -105-835-01-	Spreader rivet	3.00	2.00	new	6.00	S
9Y0-805-815-A -	bracket - fender LH	1.00	35.90	bt	35.90	S
N -905-584-01-	Spreader rivet	2.00	5.60	new	11.20	S
958-008-540-00-	Clip	2.00	6.10	new	12.20	S
9Y0-810-971-H -	Wheel housing liner LH	1.00	514.60	new	514.60	S
PAB-821-989- -	Bracket WHEEL HOUSING LH	1.00	46.40	?	46.40	S
PAF-038-549- -	Spreader rivet	4.00	0.80	new	3.20	S
N -905-841-02-	Bungs	2.00	1.50	new	3.00	S
WHT-004-935- -	Expander nut	10.00	2.00	new	20.00	S
N -910-570-01-	Screw	10.00	2.30	new	23.00	S
N -106-213-01-	expanding nut	4.00	2.70	new	10.80	S
9Y0-853-717-K -G2X	FRONT FENDER ARCH LH	1.00	549.10	new	549.10	S
9Y0-941-039-AA-	LED headlight LH	1.00	4,675.80	new	4,675.80	S
9Y0-941-119-A -	Gasket HEADLIGHT LH	1.00	218.60	new	218.60	S
958-941-591-11-	Control unit HEADLIGHT LH	1.00	794.80	new	794.80	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

QUOTATION

CODE: C0011
CUSTOMER: CHINA TAIPING INSURANCE (SINGAPO)
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909
ATTN: MOTOR CLAIM DEPT

PAGE NO.: 7
DOCUMENT NO.: 786
DOCUMENT DATE: 11/12/2024
POS ID: ES
PRINTED BY: Muhammad Nur Faiz
SERVICE ADV: Muhammad Nur Faiz
CSP/OP CODE: W
DEPT: 32084
WIP NO.: DS/SKJ1000K/0371
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 2222366
MODEL: PORSCHE - CAYENNE
CHASSIS NO.: WP1ZZZ9YZLDA03380
ENGINE NO.: 201632
REG NO.: SKJ1000K
REGN DATE: 24/03/2020

DESCRIPTION: Body & Upholstery

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
9Y0-941-607-B -	Protective cap LH	1.00	75.50	new	75.50	S
9Y0-941-052-A -	Fan for headlamps LH	1.00	416.20	new	416.20	S
9Y0-941-181-B -	Additional headlight LH	1.00	944.40	new	944.40	S
PAB-145-803-A -	Charge air cooler LH	1.00	1,519.60	new	1,519.60	S
PAB-145-737-A -	Pressure hose LH UPPER	1.00	315.10	?	315.10	S
PAB-145-942-00-	Pressure pipe UPPER CENTER	1.00	348.70	?	348.70	S
PAB-145-944-00-	Pressure hose connector upper	1.00	123.70	?	123.70	S
PAB-145-708-00-	Pressure hose connector lower	1.00	263.30	?	263.30	S
9Y0-971-095-GB-	BUMPER WIRE HARNESS	1.00	607.70	new	607.70	S
9Y0-971-073-K -	FRONT WIRE HARNESS LH	1.00	147.40	?	147.40	S

					Before GST	GST	Total	
	* GST Code	Rate	Service/Goods	GST				
Parts	39,076.20	O	-	-	Gross *	62,456.20	5,621.06	68,077.26
Surcharge	0.00	S	9.00%	62,456.20	5,621.06			
Labour	23,380.00				Less: Deposit **	0.00	0.00	0.00
Menus	0.00				Amount Due	62,456.20	5,621.06	68,077.26

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

** Deposit tax invoice No.:

*This estimate is valid for a period of thirty (30) days only.

*Prices are subject to change without prior notice.

Eurokars Services Pte Ltd

Customer signature

Authorised signature

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	02/12/2024 18:19 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	30/11/2024 11:49 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG BUKIT TIMAH ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKJ1000K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	BRYAN NG SHI EN
NRIC No	SXXXX120G
Email Address	doreen@chyejoo.com.sg
Mobile Phone No	(Phone) +65-91371933
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Porsche
Model	Cayenne
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2995
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	-

DRIVER

Name of Driver	BRYAN NG SHI EN
NRIC No	SXXXX120G
Date Of Birth	02/09/1992
Occupation	Indoor
Driving Pass Date	05/11/2018
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	6 YEARS
Gender	Male
Mobile Number	(Phone) +65-91371933
Alt. Phone Number	-
Email Address	doreen@chyejoo.com.sg
Address	68 Binjai Park
Address complement	-
Postcode	589869
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	BRENDA HEW
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBC8794A
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

WITNESS DETAILS

WITNESS 1

Name	CHAN & CHAN CONSTRUCTION SITE
Phone	-
Email	-

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims,
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/HIN No.:

2. Accident Report Form (GIA) 1/1

SKETCH PLAN

See attached Video.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

LICENSE PLATE NO: SKJ1000k

ACCIDENT DATE: 30/11/2024

CONTACT NUMBER: 91371933

ACCIDENT TIME: 11:49am

EMAIL: bryanngshien92@gmail.com

LOCATION: along bukit timah road

I was driving along bukit timah road towards binjai park. There was a lane closure on the third lane due to construction works by PUB and main contractor Chan and Chan. While i was driving, the lorry driver attempted an illegal U-turn as he was trying to enter the lane closure on the third lane. The lorry driver drove his car directly into my car resulting in the accident. I had braked hard and stopped in time, but he drove into me regardless.


NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.


PLEASE CHECK YOUR POLICY FOR MORE INFORMATION


PLEASE STATE ☐ CLAIM OWN POLICY ☒ CLAIM THIRD PARTY ☐ REPORTING ONLY

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: