

VEHICLE CONDITION REPORT FORM






Date: 30/11/24
 Technician Name: NUTHAN 48902
 Case No. 1066848 - SKT10007
 Odometer Reading (customer Vehicle): 109591
 KM travelled by Assistance vehicle: _____
 Fault Found: Accident

Customer's Name: MR. BRYAN NG SHI EN
 Customer's contact name: 9137-1933
 Make: PORSCHE Model: CAYENNE Colour: _____
 Location: 68. Binjai Punc.
 Providers' arrival time: 1600
 Job completion time (RSA): 1600

Hubcaps Y/N
 Spare Wheel Y/N
 Tools (Jack) Y/N
 Audio System Y/N
 Speakers F / R
 Keys + Remote Y/N
 Aerial Y/N
 Fuel 700km

Legend	
S - Scratch	L - Loose
D - Dent	C - Crack
B - Broken	BE - Bent
RSA	
Towing /	<u>L</u>
Others	

Day / Night Wet / Dry Clean / Soiled



All removable items of value should be removed & noted separately

Delivery to Dealership (Date/Time): 30/11/24 1600 AM/PM
 Name/Address: 27A. Tanjong Penhurel
 Vehicle received in the above condition: YES/NO Level 5

Remarks

XAAI

Customer Declaration

- I shall be responsible for the cost or additional cost of towing, in the event when I am not covered or fully covered for the service rendered
- I accept that any roadside repairs will be of a temporary nature and that advice of an authorized workshop should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- At the time of the signature, both parties agree on the vehicle existing condition and that any liability assessment for vehicle eventual damages will be based on this form.

Customer Signature	<u>27.02.24</u> <u>30/11/24</u>	Provider Signature	<u>Key art</u> <u>Utter max.</u>	Operator Signature	<u>my</u>
--------------------	------------------------------------	--------------------	-------------------------------------	--------------------	-----------