

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/10524/20183/4063

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: G3M 7340E

at Workshop m/s Precise 10am

of

Insured: G3E 2567T

Policy No. \_\_\_\_\_

Claims No. DMCF2400109H/02/CT

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$ 90k.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 100% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS C134W

Date: \_\_\_\_\_ Person Contacted: LIAISON

Vehicle: IN / OUT

Veh No: G3M 7340E Yr Regn: 28/10/24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: OPEL Combo - E C.C. 100kw

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 002877 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WOVEA2KX2PJS-43396

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/65 R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 9 mm R/Bal. 9 mm

L/Bal. 9 mm L/Bal. 9 mm

D.O.A. 12/11/24 D.O.I. 3/1/25

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

10/3/28 P/P &amp; 2073 information log (red 720, 25%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: 3

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI.

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) \_\_\_\_\_)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	134W
Vehicle Details	
Vehicle No.:	GBM7340E
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2025
Vehicle Make:	OPEL
Vehicle Model:	COMBO-E
Primary Colour:	White
Manufacturing Year:	2023
Engine No.:	-
Chassis No.:	W0VEAZKXZPJ543396
Maximum Power Output:	-
Open Market Value:	\$38,449.00
Original Registration Date:	28 Oct 2024
First Registration Date:	28 Oct 2024
Transfer Count:	0
Actual ARF Paid:	\$1,923.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Oct 2034
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$42,703.00
COE Rebate Amount:	\$41,910.00
Total Rebate Amount:	\$41,910.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 03 Jan 2025

OK



Home>Used Cars>Listing

All Category

Filter

2

Search

Save Search

16 Vehicles

Car Model

Any status

2024

Sort by Any Status, Date Posted (Newest)

Share

Shopping Cart

User

- 

Opel Combo-e Electric

\$102,800

Instl. \$1,354 /mth

\$10,470 /yr

28-Oct-2024

(9yrs 9mths COE left)

N.A

1 Owner

Fuel Type: Electric

Fully electric! Auto start and stop button with eco friendly technology! Comes with agent warranty 8 years/160,000km battery warranty, 3 years/160,000km vehicle warranty and full agent accessories! No gimmicks! High loan! High trade in! Call now to enquire!

SG Motor Link Pte Ltd|Posted 03-Jan-2025

Compare
- 

Opel Combo-e Electric

\$95,300

Instl. \$1,256 /mth

\$10,030 /yr

04-Jul-2024

(9yrs 6mths COE left)

N.A

2 Owners

Fuel Type: Electric

The EV with the most slick look! Auto start/stop button! Up to 300km per full charge! Cutting edge eco-friendly technology! Minimize your costing, maximize your earnings! One-stop solution for all your commercial vehicle needs! Contact our resourceful salesperson for any enquiries and we will make sure all your questions are answered! Call now to make appointment to view your next vehicle!

Lek Auto Pte Ltd|Posted 03-Jan-2025

Compare
- 

Opel Combo-e Electric

\$98,000

Instl. \$1,291 /mth

\$10,060 /yr

30-Sep-2024

(9yrs 8mths COE left)

N.A

2 Owners

Fuel Type: Electric

The EV with the most slick look! Auto start/stop button! Up to 300km per full charge! Cutting edge eco-friendly technology! Minimize your costing, maximize your earnings! One-stop solution for all your commercial vehicle needs! Contact our resourceful salesperson for any enquiries and we will make sure all your questions are answered! Call now to make appointment to view your next vehicle!

Compare

# PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-34 AUTOBAY SINGAPORE 417883

TEL : 67457367 FAX : 68413390

CO. REG. NO. : 35766600C

GST REG. NO. : 35766600C

05-03-2025

Accident Date : 12/11/2024

OUR REF : GBM 7340E/T/24

Full House Interior Render Pte Ltd

1 Soon Lee Street

#04-23

Singapore 627605

ESTIMATE BILL ON VEH. NO. : GBM 7340E

MODEL : OPEL COMBO

CHASSIS NO. : W0VEAZKXZPJ543396

## LIST ITEM

Rear Bumper	2e/ torn	900.00	✓
Rear Bumper Parking Sensor LH Center	Damage	190.00	✓
Rear Bumper Reinforcement	Bent	680.00	✓
		1,770.00	
		Less Discount 10%:	177.00
			1,593.00

## LABOUR CHARGE

To Reprogramming Reverse Sensor	300.00	30
To Respray Affected Areas	450.00	250
To Renew Damaged Parts, Straightened, Repair Rear End Panel and Aligned All Parts	450.00	200
	2,793.00	
	GST 9%:	251.37
	<b>AMOUNT DUE :</b>	<b>3,044.37</b>

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not fullert  
in  
mms

3/1/25

P/P \$ 2073 /  
3 days