

REF: CS1/LPM24120188/Enh3 (SJT 3131L)

Special Instruction:

ASSIGNMENT (Office)

From (Person): MUHAMAD HANIFF HANI of LPM Date/Time: 12/12/2024
Estimated Cost: _____ Bill to: _____

P/P : \$ 21,846.19 / REPAIR : 18 WORKING DAYS

Third Parties:

Claimant:

Surveyor: CA APPRAISER PTE LTD

Workshop: AE AUTO PTE LTD

OD/TP Re-inspection Evaluation

To Inspect Vehicle No: SJT 3131L Insured: JPR 8674

at Workshop m/s AE AUTO PTE LTD

of 160 SIN MING DRIVE #06-01 SIN MING AUTOCITY SINGAPORE 575722

Policy No: _____ Claim No: 19/19/19/VP02/296887

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/10/2019
(Client's Record)

H.O.D. Endorsement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: 16/12/24 Confirmed with _____ Final Fig _____, ____ days (Red \$ ____/____%; Original! ____ days)

Date/Time: 16/12/24 Submit Final Fig 9100, 8 days (Red \$12746.19 / 58 %; Original days)

[illegible]

Para(1) : Parts found not replaced (To highlight *R or UB, LR, Etc*)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)	
--	--

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Date:

Basic & Add

Transport

Photos

Others

Total

1) Date/Time _____ File Pass to _____ 2) Date/Time _____ File Return to _____
3) Date/Time _____ File Pass to _____ 4) Date/Time _____ File Return to _____
5) Date/Time _____ File Pass to _____ 6) Date/Time _____ File Return to _____