

ASS. REC. BY: Taufik

REF: CS/FC124120196/7n h3

ASSIGNMENT

COE: 2028/08

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$7200

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: FBH 6881T Yr Regn: 2013, 08

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Yamaha YZF-R15 c.c. 150

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ME11CK04702010001

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD A/Rlm or

Tyre Size: F: 110/70R17

R: 140/70R17

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 5 Rear: 5

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. D.O.I. 13/12/24

Survey held at Project Motors

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufikh confirmed lump sum \$2800 and 3 days (red. \$1164.7, 29%)

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: 3

i) _____

☐ : Final Report

Re-survey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / L.B.F. (F _____)



Quotation

6 Gambas Way, ASCENT@Gambas
#07-08, Singapore 756939
HP: 8750 1811, UEN: 53192490D

Vehicle Make : **YAMAHA**
Vehicle Model : **R15 V2**
Vehicle Year : _____

Date : **10/12/2024**
Vehicle Plate : **FBH6881T**
Owner Name : **Auzafiq**
Owner Mobile : **87525113**

S/N	Description	Qty	Amount (\$)
1	Front Cowling Set (Come w/ LH & RH Side Outer Fairing)	1 set	\$280.00 <i>cut</i>
2	Front Cowling Bracket	1 pc	\$95.00 ?
3	Front Winglet	1 pc	\$58.00 <i>cut</i>
4	Winglet Set	1 set	\$85.00 <i>cut</i>
5	Right Hand Side Inner Fairing	1 pc	\$130.00 <i>cut</i>
6	View Mirror (Come in Set & Built In Signal Light)	1 set	\$65.00 <i>cut</i>
7	Front Fork Balancing <i>desmonte photo.</i>	2 pcs	\$180.00 <i>120?</i>
8	Steering Cone	1 set	\$98.00 ?
9	Front Brake Master Cylinder Pump	1 pc	\$220.00 x
10	Front Brake Lever Guard	1 set	\$85.00 <i>cut</i>
11	LH Side Pole Light Rubber Cover	1 pc	\$15.00 ?
12	LH Side T10 Bulb	1 pc	\$8.00 ?
13	RH Side Pole Light Rubber Cover	1 pc	\$15.00 <i>cut</i>
14	Front Wheel Axle	1 pc	\$32.00 ?
15	Front Wheel Bearing	2 pcs	\$38.00 ?
16	Front Brake Disc	1 pc	\$110.00 ?
17	RH Side Handle bar	1 pc	\$68.00 ?
18	Tank Cover Set (Come w/ Tail board Complete)	1 set	\$280.00 <i>cut</i>
19	Rear Fender Bracket	1 pc	\$75.00 x
20	RH Side Lower Fairing	1 pc	\$68.00 <i>cut</i>
21	Spray Paint	1 pc	\$480.00 <i>300</i>
22	LH Side Pillion Footrest Bracket	1 pc	\$35.00 x
23	Footrest Set	1 pc	\$240.00 <i>60</i>
24	Rear Brake Switch	1 pc	\$38.00 x
25	Frame Protector Set (Carbon Fibre)	1 set	\$330.00 <i>cut</i>
26	Exhaust Protector	1 pc	\$78.00 <i>cut</i>
27	Labour	1	\$480.00 <i>300</i>
28	Towing Fee	1	\$120.00 <i>80</i>
29	I/U Unit	1 pc	\$158.70 <i>cut</i>
30			
Total Amount (\$)			\$3,964.70

Remarks

*Tanfikh 97495749 / 62563561 3 days
WP 13/12/24 0430pm. Resurvey after repair
tanfikh@lkkauto.com.*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: