

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	MS FIRST CADITA				
1	VISTINST CALLIA	L INSURANCE LTD	Ref:	CS/FCI24120196/Tnh3m4(N)	
#	16 RAFFLES QUA` #42-01 HONG LEO 048581	Y NG BUILDINGSINGAPORE	Date:	11/11/2025	
ļ ,	ATTN: JOANNE YO	ONG	Code:	FCI2	
1.	Policy Particulars :- THIRD PARTY CLAIM				
I	nsured Veh.	SH 6184X	Veh. Inspected	FBH 6881T	
F	Policy No.	D-24101861MFCT	Coverage (\$)	0.00	
	Claim No.	D24010282MFCT	Excess (\$)	0.00	
-	Assign From	CAROLINE	Assign Date	13/12/2024	
2. Vehicle Particulars & Condition					
N	Make & Model	YAMAHA YZF-R15	c.c	150	
E	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	ME11CK047D2010001	Colour	BLACK	
	Odometer	-	Steering	IN ORDER	
E	Brakes	IN ORDER	Modification	NIL	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
F	R/H Front Tyre	110/70R17	DUNLOP	5 mm	
L	L/H Front Tyre			mm	
F	R/H Rear Tyre	140/70R17	DUNLOP	5 mm	
L	L/H Rear Tyre			mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.				
	DAMAGES SEE DETAILS.				
5.	. General Information				
	Accident Date	21/11/2024	Inspection Date	13/12/2024	
5	Survey held at	PROJECT MOTORS			
		6 GAMBAS WAY #07-08, ASCENT @ GAMBAS SINGAPORE 756939			
5a.	Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
E	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				