



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

STRIDES PREMIER AUTOMOTIVE SERVICES PL	INV No.	AC2503947
60 WOODLANDS INDUSTRIAL PARK E4	INV Date	24/06/2025
SINGAPORE 757705	Reference	CS/SMR24120197/Evh3e2
ATTN: HUA YEN	Code	SMR

PROFESSIONAL SERVICE FEE

Vehicle No.	SLR 3880U
Insured Veh.	SHB 262E
Claim No.	TAX/12/24/2023
Policy No.	
Accident Date	06/12/2024
Inspection Date	13/12/2024

Description	Total
Survey Inspection	128.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES PREMIER AUTOMOTIVE SERVICES PL 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 ATTN: HUA YEN			Ref: CS/SMR24120197/Evh3e2(N) Date: 24/06/2025 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 262E	Veh. Inspected	SLR 3880U
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/12/24/2023	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	12/12/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VIOS	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MHFB29F3302013780	Colour	SILVER
	Odometer	115292 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	KAPSEN	5 mm
	L/H Front Tyre	195/50 R16	KAPSEN	5 mm
	R/H Rear Tyre	195/50 R16	KAPSEN	5 mm
	L/H Rear Tyre	195/50 R16	KAPSEN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/12/2024	Inspection Date	13/12/2024
	Survey held at	ZOOM AUTOWERKS PTE LTD 15 KAKI BUKIT RD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 3880U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOTLID	NOT NECESSARY	985.70	-
2	REAR BOOT HINGES	NOT NECESSARY	171.40	-
1	REAR BOOT INNER TRIM	NOT NECESSARY	188.50	-
2	REAR BOOT LAMPS	NOT NECESSARY	868.90	-
1	REAR BOOT LOCK	NOT NECESSARY	145.00	-
1	REAR BOOT LOCK CATCH	NOT NECESSARY	60.30	-
1	REAR BOOT LOGO	NOT NECESSARY	89.70	-
1	REAR BOOT RUBBER	NOT NECESSARY	145.70	-
1	REAR BOOT "TOYOTA" EMBLEM	NOT NECESSARY	80.30	-
1	REAR BOOT "VIOS" EMBLEM	NOT NECESSARY	75.70	-
1	REAR BOOT OUTER CHROME MOULDING	NOT NECESSARY	288.50	-
2	REAR TAILLAMP	NOT NECESSARY	1,230.00	-
1	REAR END PANEL	DENTED	777.40	620.00
1	REAR END PANEL INNER GARNISH	NOT NECESSARY	200.30	-
1	REAR KEYLESS SENSOR	NOT NECESSARY	185.20	-
1	REAR BUMPER	DENTED	879.60	558.10
2	REAR BUMPER TOP BRACKETS	NOT NECESSARY	181.80	-
2	REAR BUMPER SIDE BRACKETS	NOT NECESSARY	97.00	-
2	REAR BUMPER REFLECTORS	NOT NECESSARY	120.20	-
1	REAR BUMPER REINFORCEMENT	DENTED	415.00	323.00
2	REAR BUMPER REINFORCEMENT STAYS	NOT NECESSARY	161.00	-
2	REAR BUMPER SIDE RETAINERS	BROKEN	130.00	130.00
	LESS 25% DISCOUNT		-1,869.30	-407.78
			5,607.90	1,223.32
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	REAR NUMBER PLATE WITH HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR REVERSE SENSOR (SN)	BROKEN	350.00	200.00
			450.00	230.00

Report Ref No. CS/SMR24120197/Evh3e2(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REPLACE DAMAGED LAMPS & CHECK UP WIRING.		80.00	30.00
	TO REMOVE & REFIT INNER GARNISHES.	NOT NECESSARY	180.00	-
	TO REMOVE & REFIT REAR REVERSE SENSOR.		180.00	30.00
	TO TRANSFER REAR TAILGATE MECHANISM & WIRING ASSEMBLY.	NOT NECESSARY	80.00	-
	TO APPLY UNDERCOATING.		200.00	30.00
	PANEL BEATING.		1,500.00	800.00
	TO RE-SPRAY THE AFFECTED AREAS.		1,400.00	600.00
			3,620.00	1,490.00
	GRAND TOTAL		9,677.90	2,943.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,350.00

Report Ref No. CS/SMR24120197/Evh3e2(N)

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	09/12/2024 16:45 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	06/12/2024 09:55 (SGT)
Exact Location of Accident	Neil Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR3880U
-----------------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SIAH BOON HOCK
NRIC No	SXXXX709F
Email Address	ELIN.CQW@GMAIL.COM
Mobile Phone No	(Phone) +65-96911685
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Vios
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1496
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5137935673-01

DRIVER

Name of Driver	SIAH BOON HOCK
NRIC No	SXXXX709F
Date Of Birth	24/07/1974
Occupation	Indoor
Driving Pass Date	21/02/1995
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	29 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96911685
Alt. Phone Number	-
Email Address	ELIN.CQW@GMAIL.COM
Address	433 CLEMENTI AVE 3
Address complement	#08-250
Postcode	120433
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACH

ATTACHMENT(S)


Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHB262E
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



1


Describe Circumstance of the Accident

- Refer to Police Report -

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



**SINGAPORE
POLICE FORCE**



T/20241206/7078

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20241206/7078

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 06/12/2024 14:30		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: SIAH BOON HOCK			Address: 433 CLEMENTI AVENUE 3 #08-250 SINGAPORE 120433		
ID Type / ID No.: NRIC NO / S7423709F			Contact No.: Home/Office: Mobile: 96911685		
Nationality: SINGAPORE CITIZEN			Email: CHARCOAL1199@GMAIL.COM		
Sex: Male	Age: 50	Date of Birth: 24/07/1974	Type of Informant: Driver		
Race: Chinese			Language: English		
Occupation: Crane operator (on-site)			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 06/12/2024 09:55	Type of Location: Straight Road
Location: KAMPONG BAHRU ROAD				
Weather: Clear		Road Surface: Dry		
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB262E	Motor car				Slightly Damaged	0
SLR3880U	Motor car	TOYOTA	VIOS 1.5E CVT	Silver	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective Date	Expiry Date
SLR3880U	NTUC Income Insurance Co-Operative Limited	5137935673-01	14/08/2024	13/08/2025



**SINGAPORE
POLICE FORCE**



T/20241206/7078

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20241206/7078

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	SIAH BOON HOCK	ID No.	S7423709F
Related Vehicle	SLR3880U (Motor car)	Contact No.	96911685
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	06/12/2024	Date Discharge	06/12/2024
No. of Days granted Medical Leave (MC)	03	Degree of Injury	Slight

Brief Details.

ON 06/12/2024 AT ABOUT 09:55HR, I WAS DRIVING MY VEHICLE - SLR3880U, ALONG NEIL ROAD HEADING TOWARDS KAMPONG BAHRU ROAD. I STOPPED BEFORE THE GIVE-WAY LINE TO CHECK ON ON-COMING TRAFFIC BEFORE PROCEEDING. VEHICLE NUMBER - SHB262E, COULDN'T STOP IN TIME AND COLLIDED ONTO MY VEHICLE'S REAR PORTION. SUBSEQUENTLY, I SOUGHT FOR MEDICAL ATTENTION AT AVENT MEDICAL CLINIC AND WAS GIVEN 3DAYS MC.



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20241206/7078

3 of 3

Report No. T/20241206/7078

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 06/12/2024 14:30
Officer In Charge Of Case: TP / AEIT / CHUA SOON KEONG Contact No.: 65476030	Classification Of Case:

NP168

PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U





PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U



PHOTOGRAPHS FOR VEHICLE NO. : SLR 3880U

