ASS. REC. BY: Steve

REF:

CS/SMR24120198/Enh3

ASSIGNMENT

From: Date:	Veh No: SMT 4053L Yr Regn: 09/06/2020
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Hyundai QX Venue c.c 1598
at Workshop m/s	Colour Orange A/C: Insured / Std / NI / NA
of	Sp.Reading 93034 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: KMHRC813TLU052718
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 215/55R17
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 7 days Res.: Yes or No	D.O.A. 11/12/24 D.O.I. 16/12/24
Lum Sum: % 3 Val.: Yes or No	Survey held at Biforst
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV - \$80k	
Kindly refer our finalize \$6200.00	(L/S, before GST). 7 days.
(red, \$8590, 58%)	
7	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 7
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	
, ————————————————————————————————————	: Interview (\$) Photos
Reporter:	: Tech. Invs (\$) Others
Lump Sum / LB J: (%)	: Weel end (\$
	TOT9