

ASS. REC. BY: Taufikh

REF: CS/CT1 24070018/TvH3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☒ WS ☒ TP RES ☒ OD RES ☒ EVA ☒ INV ☒ MV ☒

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SNQ 134S

Policy No. _____

Claims No. SNM24D203635

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$155K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seent: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sumt: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Winnil Vehicle: IN / OUT

Veh No: CSL8848L Yr Regn: 2017, 07

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make: BMW X5 c.c. 2979

Colour: Silver A/C: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Sp. Reading: 175523 T/Radio: ☒ Insured / ☐ Std / ☐ NI / ☐ NA

Eng/No: _____

C/No: WZAKR020600546379

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Modl: ☒ Nil / ☐ Std / ☐ A/Rlm or

Tyre Size: F: 275/40R20

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/7/2024 D.O.I. 01/07/24

Survey held at Performance

Des. of Damages: ☒ Frt / ☐ Rear / ☐ S/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
16/10/24	Taufikh confirmed final fig \$32,590.65 (Red 6940.55, 18%)

Date/Time, File Pass to?

☐ : Prel. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 15

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Wheel and (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$ _____

Photos

Others

Rep. Format: _____

Lump Sum / L.B. / L.F. _____

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Tow In 27/6
Survey 28/6

26 June 2024

Estimate No. : b1 70264
Date Estimated : 24/06/2024
Prepared By : Yap Mee Key

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Lee Mui Hong
106 Westwood Crescent

Singapore 648797

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJL8848L	WBAKR020600S46379	18/07/2017	X5 xDrive35i	150595

DESCRIPTION

To tow accident vehicle to PML workshop.

VALUE

150.00

To replace bonnet, front bumper, front left fender, air duct, support, side mirror left assy, wheel arch, make good front left door and attachments. 850

following invoice ?
2550

4,675.00

To respray bonnet, front bumper, front left fender, wheel arch, front left door, side mirror cover and affected areas.

4,702.00

To carry out body cavity preservation.
(Per panel). 2x

118 236.00

To check electrical wiring system and lighting at the frontsection for proper function.

177.00

To replace left headlamp.

481.00

To replace left fog lamp including remove attachments to facilitate repair and conduct check for proper function.

266.00

To replace front PDC sensor wire harness including reset and conduct check for proper function.

266.00

To remove and install headlight washer and pump assembly to facilitate repairs.

531.00

Sundries.

150.00

Total Labour 1: 11,634.00

DESCRIPTION

C-CLIP NUT SELF-LOCKING
BONNET

QTY	PRIC
20	1.00
1	3,024.65

VALUE
20.00
3,024.65

Performance Motors Limited

A Sime Darby Motors Company

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 70264
Date Estimated : 24/06/2024
Prepared By : Yap Mee Key

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJL8848L	WBAKR020600S46379	18/07/2017	X5 xDrive35i	150595

DESCRIPTION	QTY	PRIC	VALUE
BONNET LH HINGE	1	143.40	143.40
Supporting strut left	1	1,166.40	1,166.40
FRT SHOCK ABSORBER	1	92.95	92.95
GRILL SIDE CLOSED LH	1	98.90	98.90
TRIM GRILLE SIDE LH (PURE EXCELLENC	1	102.35	102.35
LH COVER SPRAY NOZZLE PRIMED	1	62.75	62.75
FRT BUMPER PANEL PRIMED (PDC/CAM/SR	1	1,747.70	1,747.70
LOWER TRIM PANEL (PDC/SCHWARZ)	1	325.40	325.40
PLUG	20	1.60	32.00
FRT LH GRILLE (PURE EXCELLENCE)	1	185.95	185.95
FRT RH GRILLE (PURE EXCELLENCE)	1	185.95	185.95
EMBLEM GROMMET	1	0.95	0.95
BMW PLAQUE WITH ADHESIVE FILM	1	75.80	75.80
LH MIRROR GLASS HEATED WIDE ANGLE	1	237.30	237.30
LH OUTSIDE MIRROR COVER CAP PRIMED	1	167.20	167.20
LH EXTERIOR MIRROR W/O GLASS HEATED	1	1,519.05	1,519.05
V STRUT LEFT	1	64.05	64.05
SUPPORT HEADLIGHT LH	1	180.10	180.10
MODULE CARRIER LH	1	156.60	156.60
LH SIDE PANEL CENTRE BRACKET	1	44.15	44.15
FRT LH REINFORCEMENT SIDE PANEL	1	97.00	97.00
FRT LH SIDE PANEL	1	1,436.35	1,436.35
ENGINE COMPARTMENT SHIELDING FRT	1	391.95	391.95
FRT ENGINE HOOD SEALING	1	64.05	64.05
LH ENGINE HOOD SEALING	1	36.30	36.30
FRT LH WHEEL WELL TRIM PCS PRIMED 1	1	312.10	312.10
FRONT LEFT Repair wiring	1	757.60	757.60
Fanfare horn	1	93.90	93.90
LH SPRAY NOZZLE	1	201.50	201.50
HOSE LINE HEADLIGHT CLEANING SYSTEM	1	87.60	87.60
LH HEADLIGHT LED TECHNOLOGY	1	5,435.90	5,435.90
LH FOG LIGHT LED	1	501.05	501.05
DECOUPING RING PDC TORQUE CONVERTER	1	5.55	5.55
ULTRASONIC SENSOR GLACIERSILBER(WA8	1	383.65	383.65

Total Parts : 19,438.10



Tanjiu 97495749 / 62563561
WP 11/7/24 e 445pm
11P Resurvey before paint.
tanjiu e thkando.com
of day

Labour 1	:	11,634.00
Parts	:	19,438.10
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	2,796.49
Grand Total	:	33,868.59

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

 SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	24/06/2024 17:27 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	22/06/2024 17:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	OUTSIDE 147 WESTWOOD CRESENT
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL8848L
INSURED/POLICYHOLDER	
Is company?	No
Name of Registered Owner	LEE MUI HONG
NRIC No	SXXXX382A
Email Address	JIAJIELEONG@GNAUKL.COM
Mobile Phone No	(Phone) +65-97310383
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	BMW
Model	X5
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2998

INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	D24MTPV01001252

DRIVER

Name of Driver	LEONG JIA JIE
NRIC No	SXXXX692J
Date Of Birth	24/12/1997
Occupation	Indoor

Driving Pass Date	13/01/2017
Driving experience	7 YEARS AND 5 MONTHS
Gender	Female
Mobile Number	(Phone) +65-83397997
Alt. Phone Number	-
Email Address	JIAJIELEONG@GMAIL.COM
Address	109 WESTWOOD CRESCENT
Address complement	-
Postcode	648797
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Opening Door of Vehicle
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	Q

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SNQ134S
Vehicle Manufacturer	BMW
Vehicle Model	316i
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-93205616
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed.
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Yap Mee Key
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941


ON BEHALF
Policyholder's Signature
Date & Time: 24/6/24


Driver's Signature
(if driver is not the policyholder)
Date & Time: 24/6/24


Reporting Centre Personnel's Signature
Name
NRIC/FIN No..

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along my estate, heading out, when out of a sudden, the driver of SNQ1395 suddenly opened his door without checking for oncoming traffic. It was right at the time when I was beside him and I slammed into his door as I had no time to react. Also, the roads in my estate is very narrow as there are many cars parked along side of the road, which further calls on every driver to check for oncoming traffic before opening doors, there were also no other cars in motion along the stretch of road besides me.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] ON BEHALF

Policyholder's Signature

Date & Time: 24/6/24

[Signature]

Driver's Signature

(if driver is not the policyholder)

Date & Time: 24/6/24

Yap Hwee Key

Performance Motors Limited

303 Alexandra Road

Singapore Performance Centre

Singapore 159941

[Signature]

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: