

ASS. REC. BY:

REF:

AG21 230066371KV

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SKH 8114E

Policy No.

Claims No. C10023182/SR

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

WC 4994S

Yr Regn:

04, 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Zuzu CYH

C.C.

15681

Colour

White/Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

474784

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JALCYH 52SC 7000070

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

Unicom 295/80R22.5

R:

Top runner

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / (C)

TOYO / YOKO or

APIW

Front

R/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

30/6/23

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12/7 11:00 @ 5800 confirmed (Red 7833.55, 57%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 12/7/23-typist

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

: Photos

: Others

TOTAL

Report Format: TP

Lump Sum / LB: (\$ 5800)

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 301C

### Vehicle Details

Vehicle No.: WC4994S  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 03 Jul 2023  
Vehicle Make: ISUZU  
Vehicle Model: CYH52S  
Primary Colour: Blue  
Manufacturing Year: 2012  
Engine No.: 6WG1416315  
Chassis No.: JALCYH52SC7000070  
Maximum Power Output: -  
Open Market Value: \$137,217.00  
Original Registration Date: 18 Apr 2012  
First Registration Date: 18 Apr 2012  
Transfer Count: 1  
Actual ARF Paid: \$6,861.00

### Intended PARF Rebate Details

PARF Eligibility: No  
PARF Eligibility Expiry Date: -  
PARF Rebate Amount: \$0.00

### Intended COE Rebate Details

COE Expiry Date: 17 Apr 2027  
COE Category: C - Goods Vehicle & Bus  
COE Period(Years): 5  
PQP Paid: \$23,008.00  
COE Rebate Amount: \$17,434.00  
Total Rebate Amount: \$17,434.00

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 03 Jul 2023

OK

SF0F23730001 / FALCON-AIR AUTO SERVICES PTE LTD [575721]  
ENTRY DATE & TIME: 03/07/2023 11:48 (SGT)  
SUBMITTED BY: Jacqueline Ng  
VERSION: 1 (03/07/2023 11:48 (SGT))

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	03/07/2023 11:48 (SGT)
Reported by	Actual Driver
Date of Accident	30/06/2023 16:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	YISHUN AVE 3
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	WC4994S
-----------------------------	---------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BHUVAN CONSTRUCTION PTE LTD
Company Reg No	201134301C
Email Address	ANDY.LEE@PAS.SG
Mobile Phone No	(Phone) +65-92366363
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Isuzu
Model	Cyh52s
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	15861

#### INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5113396825-03

#### DRIVER

Name of Driver	KARUNANITHI SURESHKUMAR
NRIC No	G8306459K
Date Of Birth	03/05/1987
Occupation	Outdoor

Date Of Driving Pass	06/02/2012
Driving experience	11 YEARS AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98101057
Alt. Phone Number	-
Email Address	ANDY.LEE@PAS.SG
Address	NA
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER SKETCH PLAN

#### REPAIR AT OWNER'S WORKSHOP

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGH2209C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

# SKETCH PLAN

- a. I have read the contents of the Police Report and I agree with the information contained therein.
- b. I have read the contents of the Police Report and I agree with the information contained therein.
- c. I have read the contents of the Police Report and I agree with the information contained therein.
- d. I have read the contents of the Police Report and I agree with the information contained therein.
- e. I have read the contents of the Police Report and I agree with the information contained therein.
- f. I have read the contents of the Police Report and I agree with the information contained therein.
- g. I have read the contents of the Police Report and I agree with the information contained therein.
- h. I have read the contents of the Police Report and I agree with the information contained therein.
- i. I have read the contents of the Police Report and I agree with the information contained therein.
- j. I have read the contents of the Police Report and I agree with the information contained therein.
- k. I have read the contents of the Police Report and I agree with the information contained therein.
- l. I have read the contents of the Police Report and I agree with the information contained therein.
- m. I have read the contents of the Police Report and I agree with the information contained therein.
- n. I have read the contents of the Police Report and I agree with the information contained therein.
- o. I have read the contents of the Police Report and I agree with the information contained therein.
- p. I have read the contents of the Police Report and I agree with the information contained therein.
- q. I have read the contents of the Police Report and I agree with the information contained therein.
- r. I have read the contents of the Police Report and I agree with the information contained therein.
- s. I have read the contents of the Police Report and I agree with the information contained therein.
- t. I have read the contents of the Police Report and I agree with the information contained therein.
- u. I have read the contents of the Police Report and I agree with the information contained therein.
- v. I have read the contents of the Police Report and I agree with the information contained therein.
- w. I have read the contents of the Police Report and I agree with the information contained therein.
- x. I have read the contents of the Police Report and I agree with the information contained therein.
- y. I have read the contents of the Police Report and I agree with the information contained therein.
- z. I have read the contents of the Police Report and I agree with the information contained therein.




Actual Driver's Signature (If Driver is not the policyholder) (Date & Time)



Witnessed by Reporting Centre Personnel (Name and KRRCID card)

## Sketch Plan



30057422

SKETCH PLAN #2

Incident Report (Accident Report)

Attach Accident Scene photo

Attach Accident statement

Declaration  
I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder)  
/ Date & Time



Witnessed by Recording Centre Personnel  
(No. as in NRCCD card)

vAn2022

2

SKETCH PLAN #3

On 30/6/2023 at about 4.10pm, I was driving WC4994S traveling along Sembawang Road towards Yishun Avenue 5 directions.

Before the traffic junction of Yishun Avenue 3 there is road works on the middle lane of the road. I was traveling on the right side and 3rd party SGH2209C was traveling on the left side (the road works is in between us).

After passing the road works I keep to the left and was already on the middle lane almost straight but 3rd party suddenly came from my left behind and cut into my lane. (the road works was ongoing behind us, ie the middle lane).

As a result both our vehicles collided against each other. 3rd party right rear side has hit onto my vehicle front left corner.

After the accident, we exchanged our particulars and no injuries in this accident.

3rd party driver is Goh Joo Tuan (I/C No: S2502832E).

I want to claim 3rd party for my damages.

K. Rung.

Karunanithi Sureshkumar

03/07/23

# TSR AUTOMOTIVE PTE LTD

160, SIN MING DRIVE, SIN MING AUTOCITY # 06-15  
SINGAPORE 575722

Not Authorized  
11/12/2023 8.5800  
Henry Ate Pina  
3 days

Date : 3 Jul 2023

QUOTATION - THIRD PARTY CLAIM

AUTO & GENERAL INSURANCE ( SINGAPORE ) PTE LTD

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 30 Jun 2023

VEH. No : WC 4994 S / CYH52S

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INVCOME INSURANCE

QTY	ITEM	AMOUNT	CONDITION
Third party vehicle : SGH 2209 C			

1	FRONT RH CORNER PANEL	REPAIR	
1	FRONT RH CORNER PANEL BRACKET LH	\$ 11.1 220.00	—
1	FRONT BUMPER 1800	\$ 12.1 2,900.00	—
1	FRONT BUMPER OUTER RIM LH 385	\$ 0.1 480.00	—
1	FRONT BUMPER LOWER BRACKET LH 132.50	\$ 12.1 220.00	—
1	FRONT BUMPER LAMP LH	\$ 12.1 385.00	—
1	HEADLAMP LH 980	\$ 12.1 1,285.00	—
1	HEADLAMP INNER HOLDER BRACKET LH	\$ 12.1 980.00	—
1	SIGNAL LAMP LH 185	\$ 12.1 580.00	—
1	FRONT LH STEP HOUSING TOP	\$ 12.1 980.00	—
1	FRONT LH STEP HOUSING CENTER RUBBER LH	\$ 12.1 298.00	—
1	FRONT LH STEP HOUSING BOTTOM 850	\$ 12.1 1,485.00	—
12	STEP PANEL LH ( TOP AND BOTTOM ) 328	\$ 12.1 800.00	—
1	FRONT STEP HOUSING LOWER SUPPORT 1128.00	\$ 12.1 2,250.00	—
TOTAL PARTS :		\$ 12,863.00	
LESS 15%		\$ 1,929.45	
TOTAL LIST PARTS :		\$ 10,933.55	
TOTAL PARTS PRICE :		\$ 10,933.55	

AMOUNT BRING FORWARD :

\$ 10,933.55

Labour to do cutting , welding, repair , replace , align adjust  
accident affected area

\$ 1,400.00

4501

To do anti rust

LKK Auto Consultants hence notify the Repairer of the following:

\$ 120.00

X

To check wire system, focus headlamp

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

\$ 180.00

201

To do spray painting on accident area ( inner & outer )

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

\$ 1,000.00

6001

TOTAL LABOUR :

\$ 2,700.00

GRAND TOTAL PARTS & LABOUR :

\$ 13,633.55

Acknowledged by Repairer

Date: