

## LKK AUTO COIISUITATION 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI24120210/Knh3e2(N)	
		TINSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 06/02/2025	
	ATTN: CHEN HOV	V	Cod	de: AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNK 8407J	Veh. Inspected	SCX 3E	
	Policy No.	P11078210R00	Coverage (\$)	0.00	
	Claim No.	C10033465/CH	Excess (\$)	0.00	
	Assign From	LAN BOON CHIN	Assign Date	16/12/2024	
2.	2. Vehicle Particulars & Condition				
	Make & Model	BYD SEAL (A)	c.c	0	
	Engine No.	HIDDEN	Year of Reg.	2024	
	Chassis No.	LGXCH6CD3R2127806	Colour	BLACK	
	Odometer	8643 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/45 R19	CONTINENTAL	9 mm	
	L/H Front Tyre	235/45 R19	CONTINENTAL	9 mm	
	R/H Rear Tyre	235/45 R19	CONTINENTAL	9 mm	
	L/H Rear Tyre	235/45 R19	CONTINENTAL	9 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/12/2024	Inspection Date	19/12/2024	
	Survey held at	MY CAR CONSULTANT PTE LT	D		
		60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	. Estimate Days of Repair				
1	I · · · · · · ·	· · · · · · · · · · · · · · · · · · ·			

5 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: