

ComfortDelGro Engineering Pte Ltd (Co.Reg.No.199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	14/12/2024
Vehicle Reg. No.:	SHC1677E	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	30/10/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU414689	Chassis No:	KMHC851CVLU191495
Odometer:	368909 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	11,796.64
Miscellaneous Items	12.00
Labour	2,960.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	14,768.64
+ GST 9.00% (S\$)	1,329.18
Nett Amount (S\$)	16,097.82

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 16 Dec 2024)
 Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHC1677E/16/12/2024 14:14
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET ASSY / 00	20.00	0.00	*2,253.80 FL
2	2		*BONNET HINGE LH/RH - BT	20.00	0.00	*237.40 FL
3	1		*BONNET ABSORBER LH/RH	20.00	0.00	*35.70 FL
4	1		*BONNET LOCK ?	20.00	0.00	*127.30 FL
5	1		*FRONT FENDER LH / 00	20.00	0.00	*588.80 FL
6	1		*FRONT BUMPER COVER - BR	20.00	0.00	*481.10 FL
7	1		*FRONT BUMPER CENTRE MOULDING - BR	20.00	0.00	*368.50 FL
8	1		*FRONT RADIATOR GRILLE	20.00	0.00	*1,409.10 FL
9	1		*FRONT GRILLE EMBLEM ?	20.00	0.00	*48.30 FL
10	1		*FRONT RADIATOR TOP COVER - BR	20.00	0.00	*476.30 FL
11	1		*FRONT BUMPER REINFORCEMENT X	20.00	0.00	*1,136.70 FL
12	1		*FRONT BUMPER SIDE BRACKET LH/RH - BR	20.00	0.00	*35.00 FL
13	10		*FRONT BUMPER CLIPS - NPC	20.00	0.00	*22.00 FL
14	1		*HEADLAMP SUPPORT PANEL - BR	20.00	0.00	*949.30 FL
15	1		*HEAD LAMP ASSY LH / RH (LH) - BR	20.00	0.00	*2,110.30 FL
16	1		*FRONT LH DAYLIGHT X	20.00	0.00	*642.50 FL
17	1		*FRONT FENDER LH X Repaired / 117	20.00	0.00	*588.50 FL
18	1		*FRONT FENDER SHIELD LH - BR	20.00	0.00	*164.70 FL
19	1		*FRONT FENDER EMBLEM - NPC	20.00	0.00	*28.80 FL
20	2		*FRONT FENDER RETAINER LH / RH X	20.00	0.00	*82.80 FL
21	1		*RADIATOR ASSY ?	20.00	0.00	*710.50 FL
22	1		*RADIATOR INVERTOR ?	20.00	0.00	*884.80 FL
23	1		*AIR CON CONDENSER ?	20.00	0.00	*663.60 FL
24	1		*FRONT HEAD LAMP PANEL ?	20.00	0.00	*121.00 FL
25	1		*FRONT FENDER APRON PANEL LH ?	20.00	0.00	*329.00 FL
26	2		*FRONT FENDER ADVERTISEMENT LH/RH - NPC	0	0.00	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	14,695.80
- List Item Discount on L Items (\$\$)	2,899.16
Total Parts (\$\$)	11,796.64

ComfortDelGro Engineering Pte Ltd/SHC1677E/16/12/2024 14:14. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Qty	Particulars	Amount
Miscellaneous Items		
1	OD/TP Case (Insurer)	12.00
Sub Total (S\$)		12.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,900.00
2	SPARY PAINTING	New	900.00
3	CHECK WIRING AND LIGHTING	New	60.00
4	REMOVE/REFIX AIR CON & CHARGE GAS	New	100.00
Gross Labour Cost (S\$)			2,960.00

ComfortDelGro Engineering Pte Ltd/SHC1677E/16/12/2024 14:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve (LKK)

16/12/24, 3.30pm

✓ IL

L/S

by the spy

6 days

Date/Time: 16.12.2024 12:41

Page : 1

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5964334

JC NO305612848

COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO: SHC1677E	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL: IONIQ(G3)	DATE/TIME IN 14.12.2024 16:00
	YR OF MANU: 30.10.2020	TARGET DATE
	CHASSIS CODE: KMHC851CVLU191495	COMPLETION DATE/TIME:


JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 14.12.2024

ATURE: 3P 14.12.2024

NO LABOR CODE DESCRIPTION



ED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHC1677E

CHIANG

Vehicle No.: **SHC1677E**

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard