

ASSIGNMENT

Front: _____ Date: _____
 Est: _____
 OD / TP RES / OD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O 10 km/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claim's No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Velt: _____
 (Policy Condition)

N/S	O/S

Remark: Tereh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLA 8418D Yr Regn: 2016 / March

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: Hyundai Elantra C.D. 1591

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 129801 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMH D841CM H*U 102,549

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45 R17

R: 225/45 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. _____

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I. 17/12/24

Survey held at N51

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>Yes (✓) / No ()</u>
	<u>MV</u>
	<u>PV</u>
	<u>Nett</u>

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Survey Fee:

Transportation:

\$ + R.S. \$1

Photos

Others

Report Format: _____

Report Form: _____