ASS, REC. BY: Steve

REF:

CS/INC24120235/Evh3

ASSIGNMENT

From: Date:	Veh No: GBF8384J Yr Regn: 22 Mar 2017
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: NISSAN CABSTAR c.c 2953
at Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	c/No: JN1SC2F24Z0859272
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 11/12/24 D.O.I. 17/12/24
Lum Sum: % 3 Val.: Yes or No	Survey held at STYTECH
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV - \$25k	
Data Time Cite Propriet	Days Of Repair:
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: Survey Fee:
: Final Report	Transportation:
Date/Time, File Return to? Add Fe	
2)	: Interview (\$) Photos
The second Property of	:Tech. Invs (\$) Others
Repetiformat:	: Weellend (\$
Lump Sum / I.B.J: (%)	TOTAL
	: IVINL