



Home / Case management / Immediate loss advice

CONDITION OF VEHICLE AT THE TIME OF SURVEYSteering (Serviceable) ☐ Brake (Serviceable)Handbrake (Serviceable) ☐ Modification**CONDITION OF TYRES**Front Tyre Size Tyre SizeFront Left Side:(mm) Left Side:(mm)Front Right Side:(mm) Right Side:(mm)

1. Surveyor name 2. Point impact/General Description of
Damages 3. Vehicle registration date 4. Engine Capacity 5.
Repair Margin 6. Mandate request amount

1. Surveyor name : Steve Chen
2. Point impact/General Description of Damages ; o/s body
3. Vehicle registration date : 6/8/2020
4. Engine Capacity :1997cc
5. Repair Margin : mv:\$105,000.00 (est) lta: \$51,490.00 nv: \$53,510.00
6. Mandate request amount:\$34,511.90

262/5000

Repairer's Estimate(Gross) :\$ 47755.80

Revised Amount :\$ 29594.80

Check Items(Estimated) :\$ 4917.10

Total :\$ 34511.90

Less

:\$

Total Loss Considetation

New for Old Value :\$

Pre-Accident Value :\$

COE/PARF Rebate :\$

Salvage Value :\$