

ASS. REC. BY: Taufik

REF: CS/SMRT24120245/Tqp3

### ASSIGNMENT

(OE: 2027) 04

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     | X   |

Bal. or Market Value: \$20K

IDAC Accident Report \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seent \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: GRA2625E Yr Regn: 2007 05

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toyota Dyna c.c. 2982

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 428971 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTFAT359X0.3000235

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: MI / S/Rim / STD A/Rim or

Tyre Size: F: 195/R15

R: 155/R12

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or Falken

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 18/12/25

Survey held at Ban Choon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time \_\_\_\_\_ Action / Instruction \_\_\_\_\_

Taufik finalised LS \$3400, 5 days (Red \$1900, 36%)

Date/Time, File Pass to?

☐ : Prell. Report

1) 20/01 Typist

☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

Report Format: TP

Lump Sum / H.B. / 3400



# 萬 春 摩 哆 BAN CHOON MOTOR WORKS

Blk 3, Pioneer Road North #01-14/15 Singapore 628457

Tel: 6264 1191 Fax: 6261 1324

E-mail: banchoon@singnet.com.sg

Business Reg./GST Reg. No. 351915/00A

**GST Regn No. 35191500A**

17/12/2024

MS First Capital Insurance Ltd  
36 Robinson Road  
#16-01 City House  
Singapore 068877

Attn: Motor Claim Dept.

Dear Sir/Madam

QUOTATION FOR REPAIRS OF VEHICLE NO. GBA 2625 E  
MODEL: TOYOTA DYNA  
DATE OF ACCIDENT: 13/12/2024  
YOUR INSURED VEHICLE NO. SBS 6081 C

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

|      |                           |
|------|---------------------------|
| 1 pc | Tailgate                  |
| 1 pc | RH side gate              |
| 1 pc | TOYOTA logo               |
| 1 pc | Rear number plate bracket |
| 1 pc | Rear stepping board       |
| 1 pc | 13 PAX sticker            |
| 1 pc | 70 Km/h sticker           |
| 1 pc | Dyna logo                 |
| 1 pc | Rear number plate         |

|    |          |      |
|----|----------|------|
| \$ | 1,800.00 | Nbt  |
|    | 1,900.00 | Nbt  |
|    | 180.00   | Nbt  |
|    | 80.00    | Nbt  |
|    | 120.00   | Nbt  |
|    | 25.00    | SNbt |
|    | 25.00    | SNbt |
|    | 35.00    | SNbt |
|    | 35.00    | SNbt |
| \$ | 4,200.00 |      |

## LABOUR CHARGES:

To knocking and straightening of all necessary damaged parts.

To changing of the above parts.

To putty and spray painting on accident damaged parts.

|    |          |      |
|----|----------|------|
|    | 600.00   | 500  |
|    | 500.00   | ✓    |
| \$ | 5,300.00 | 1000 |

Yours faithfully,

Palindya

Tanpin 97495745/62563561  
WP 18/12/2024 3pm  
c/s Resurvey after repair  
straightening & painting  
4-5 days

|         |
|---------|
| 2775    |
| 500     |
| 1000    |
| 4275    |
| 4593400 |
| 05 days |