

ASS. REC. BY:

REF:

1-621

CS/FCI 24120254/Knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

- 6 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCP 75616 Yr Regn: 06.06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Altis C.C. 1598

Colour

N. Gold A/C: Insured / Std / NI / NA

Sp. Reading

408178 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Hicity 195/65R15

R: Kapsen

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

9 mm

Rear

R/Bal.

8 mm

L/Bal.

9 mm

L/Bal.

8 mm

D.O.A.

14/12/24

D.O.I.

19/12/202

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 LTA return @ 7097.00

20/12/1 Pump @ 3600k Cash (Red. \$ 2360.50, 3990)

Date/Time, File Pass to?

☐

Prell. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair: 6

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fuel

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	16/12/2024 16:21 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	14/12/2024 02:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	TEMASEK BOULEVARD, FOUNTAIN OF WEALTH
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCP7561G
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ZHENG HUIZHAN
NRIC No	S8233759H
Email Address	ISABEL.Z@GMAIL.COM
Mobile Phone No	(Phone) +65-96676659
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	COROLLA ALTIS 1.6 AUTO
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1598
Vehicle Fuel	Petrol
First Registration Date	30/06/2006
Chassis no	MR053ZEC107122695
Effective Date/Time of Ownership	09/12/2019 04:12 (SGT)

INSURANCE COMPANY

Name of Insurance Company	Income Insurance Limited
Policy Number / Cover Note Number	5114604988-04

DRIVER

Name of Driver	ZHENG HUIZHAN
NRIC No	S8233759H
Date Of Birth	06/10/1982
Occupation	Outdoor
Driving Pass Date	05/04/2004
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	20 YEARS AND 8 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96676659
Alt. Phone Number	-
Email Address	ISABEL.Z@GMAIL.COM
Address	BLK 315B ANCHORVALE ROAD #07-166
Address complement	-
Postcode	542315
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

NOTE: VEHICLE REPAIR AT OWNER W/SHOP

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD4497H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	ZHENG HUIZHAN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SCP7561G
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
 - i. understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 - (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

[Stamp: SUN MING] *[Signature: Florence]*
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



v3jun2022

Describe Circumstance of the Accident

At around 2:30am ~~and~~ 2:40am on 14 December (Saturday), I (SP75619) was travelling along the Suntec City Fountain on my way to pick up a passenger at the Tower 2 pick up point. I slowed down my vehicle and was at the left-most lane when my vehicle was struck on the rear right side by taxi (SHD 4497H).

The impact caused my car to jerk forward sharply. After the crash, I felt a headache and an ache on the right side of my neck and back.

Declaration

I/We declare the foregoing particulars are true in every respect.

[Signature] 16/12/24
 Policyholder's Signature / Date & Time

12:52 pm
 Actual Driver's Signature (if driver is not the policyholder) / Date & Time



[Signature]
 Witnessed by Reporting Centre Personnel

(Name as in NRIC/ID card)

CHOON HOCK MOTOR TRADING CO

18 December 2024

Not Notified
11 Amp & 3600
Recovery After Pains
6 days

ESTIMATE REPAIR BILL ON SCP7561G TOYOTA COROLLA ALTIS 1.6E VVTI AUTO

1 pce boot lid emblem	<i>Ne</i> \$ 26.00	<i>✓</i>
1 pce boot lid "COROLLA" plate	<i>ne</i> \$ 28.00	<i>✓</i>
1 pce boot lid "ALTIS" plate	<i>ne</i> \$ 35.00	<i>✓</i>
1 pce boot lid "1.6E" plate	<i>ne</i> \$ 44.00	<i>✓</i>
1 pce boot lid "VVDTi" plate	<i>ne</i> \$ 41.00	<i>✓</i>
1 pce boot rubber	<i>IL</i> \$ 188.60	<i>X</i>
1 pce rear lamps assy RH	<i>Bz</i> \$ 328.00	<i>✓</i>
1 pce rear lamp lower panels RH	<i>Bz</i> \$ 89.00	<i>✓</i>
1 pce rear panel	<i>Bz</i> \$ 722.40	<i>✓</i>
1 pce rear panel inner garnish	<i>Ad</i> \$ 168.00	<i>X</i>
1 pce rear bumper fascia	<i>CM</i> \$ 685.00	<i>✓</i>
1 pce rear bumper brackets RH	<i>Bz</i> \$ 48.00	<i>✓</i>
1 pce rear bumper side retainers RH	<i>Di</i> \$ 29.00	<i>✓</i>
1 set rear windscreen moulding	<i>ne</i> \$ 180.00	<i>✓</i>
1 pce rear fender RH	<i>Bz</i> \$ 950.00	<i>X</i>
	\$3,562.00	
less 25%	\$ 890.50	
	\$2,671.50	

SNETT/LABOUR

1 pce rear panel sealant	<i>ne</i> \$ 60.00	<i>305N</i>
1 set rear panel inner garnish clips	<i>ne</i> \$ 14.00	<i>X</i>
1 set rear bumper clips	<i>ne</i> \$ 35.00	<i>✓</i>
1 set reverse sensors	<i>se</i> \$ 220.00	<i>X</i>
1 set rear windscreen sealant	<i>ne</i> \$ 60.00	<i>X</i>
Remove and refit rear windscreen	<i>ne</i> \$ 200.00	<i>X</i>
Remove reverse sensors, refit	\$ 120.00	<i>501</i>
Wirings	\$ 60.00	<i>201</i>
Panel beating	\$ 1,200.00	<i>1000</i>
Spray painting	\$ 1,200.00	<i>8001</i>
Rustproof	\$ 120.00	<i>601</i>
Total amount :	\$5,960.50	NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L
 Tel: (65) 64530778 Email: choonhockmotor@gmail.com

Signature:
 Date:

5960.50