BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 (AfterSales) (Motorrad) Fax. 64796601 64796624



GST REG. NO : M2 - 0020081 - X

ESTIMATE

17 Dec 2024

>QX5274

Page No. : 1 of 5 Estimate No. : b1 72115

Date Estimated : 13/12/2024 Prepared By : Chua Kee Sin

PLUG IN RETAINER

ALLOY RIM 7.5X17 DOUBLE SPK 549

- ESTIMATE REPAIR FOR -- ACCOUNT -40000 Cash Sales - Service Hong Ching Chung

Singapore 37 CHEMPAKA AVENUE

SINGAPORE 349650

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL | | | MILEAGE |
|-----------|---|-------------------------|----------------|----------|-------------|-------------------|
| SNA6585T | WBA2X920407H97821 | 01/07/2021 | 216i Act: | ive Tour | rer | 34992 |
| | DESCRIPTION Replace right rear door ,right lower attachment etc and carryout necessary repairing w | | | | | VALUE 3,825.00 |
| | rear bumper Painting rear bumper,right rear side lower | e fender,right rear sid | de door ,right | | | 4,294.00 |
| | side skirting and right roof frame To carry out body cavity preservation (Per panel). | on. | | | | 118.00 |
| | To check steering geometry and co accordance with BMW specification | | ent in | | | 531.00 |
| | To check electrical wiring system a rear section for proper function. | nd lighting at the | | | | 177.00 |
| | To transfer lock mechanism from of conduct check on new door power function. (1 door). | | | | | 531.00 |
| | To check steering geometry and co accordance with BMW specification | | ent in | | | 531.00 |
| | To replace tyre and wheel rim incluright rear | ding balancing. (1x) | | | | 94.00 |
| | Sundries. | | | | | 150.00 |
| | | | | Tota | l Labour 1: | 10,251.00 |
| | DESCRIPTION | | ****** | QTY | PRIC | VALUE |

10

1

2.45

946.50

24.50

946.50

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad

(AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 72115

Date Estimated Prepared By

Page No. : 2 of 5

: 13/12/2024 : Chua Kee Sin

MILEAGE REGN. DATE MODEL REGN. NO. CHASSIS NO. 34992 WBA2X920407H97821 01/07/2021 216i Active Tourer SNA6585T

| DESCRIPTION | QTY | PRIC | VALUE |
|-------------------------------------|-----|----------|------------|
| RR RH DOOR | | 1,356.25 | 1,356.25 |
| RH LOWER REAR DOOR HINGE | 1 | 67.45 | 67.45 |
| RH UPPER REAR DOOR HINGE | 1 | 67.45 | 67.45 |
| RH SUPPORT SILL | 1 | 16.80 | 16.80 |
| REAR RH DOOR BRAKE | 1 | 84.35 | 84.35 |
| FOAM SEAL | 2 | 24.00 | 48.00 |
| REAR RH DOOR INNER WEATHERSTRIP | 1 | 60.90 | 60.90 |
| REAR RH DOOR CORNER TRIM | 1 | 64.05 | 64.05 |
| Seal, trim, | 1 | 18.15 | 18.15 |
| Seal, corner | 1 | 27.20 | 27.20 |
| RH SEALING COLUMN B BOTTOM | 1 | 62.70 | 62.70 |
| REAR RH DOOR OUTER CHANNEL COVER (A | 1 | 104.90 | 104.90 |
| REAR RH DOOR WINDOW FRAME COVER (AL | 1 | 56.75 | 56.75 |
| RR RH DOOR SOUND INSULATING | 1 | 86.30 | 86.30 |
| REAR DOOR JOINT SEAL | 1 | 36.90 | 36.90 |
| REAR DOOR EDGE PROTECTION | 1 | 181.30 | 181.30 |
| CLIP | 10 | 0.90 | 9.00 |
| RH SILL TRIM PRIMED | 1 | 204.00 | 204.00 |
| FRT RH RETAINING STRIP SILL | 1 | 113.15 | 113.15 |
| RR RH RETAINING STRIP SIDE SILL MID | 1 | 113.15 | 113.15 |
| RR RH RETAINING STRIP SILL | 1 | 94.30 | 94.30 |
| FRT RH APERTURE COVER | 1 | 44.80 | 44.80 |
| GROMMET | 2 | 5.70 | 11.40 |
| | Tot | al Parts | : 3,900.25 |

10,251.00 Labour 1 : Parts 3,900.25 Labour 2 0.00 Excess 0.00 1,273.61 Total GST @ 9%

Grand Total 15,424.86

^{**} THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

^{**} PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- 5. Into trial to the season of and that copies of this report will, for a fee, be made available upon application by interested parties.

 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

13/12/2024 10:20 (SGT) Date of First Submission Actual Driver Reported by 12/12/2024 08:00 (SGT) Date of Accident Exact Location of Accident Singapore CTE (AYE) SLIP ROAD INTO PIE (TUAS) LP 359526F Additional Location Information

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Private use

Vehicle Registration Number **SNA6585T**

INSURED/POLICYHOLDER

Is company? No

HONG CHING CHUNG Name Of Registered Owner

NRIC No SXXXX598C Email Address CC9HONG@GMAIL.COM

(Phone) +65-92379913 Mobile Phone No

Alternative Phone No

VEHICLE PARTICULARS

Manufacturer B.M.W. 216I ACTIVE TOURER Model

Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to

your vehicle? No - Claiming third party

Private car Vehicle Category Auto Transmission

1499 CC Vehicle Fuel Petrol

First Regisration Date 01/07/2021

WBA2X920407H97821 Chassis no Effective Date/Time of Ownership 01/07/2021 03:07 (SGT)

INSURANCE COMPANY

EQ Insurance Company Ltd Name of Insurance Company DMPPHQ24-006574 Policy Number / Cover Note Number

DRIVER

accident

Name of Driver
TAN CHAI HAR
NRIC No
SXXXX014A
Date Of Birth
07/01/1963
Occupation
Indoor
Driving Pass Date
29/12/1984
Driving License Pass Class
3

Driving Pass Date 29/12/1984
Driving License Pass Class 3
Driving License Validity Valid
Driving experience 40 YEARS
Gender Female

Mobile Number (Phone) +65-97803781

Alt. Phone Number
Email Address CC9HONG@GMAIL.COM

Address 37 CHEMPAKA AVENUE

Address complement Postcode 349650
Is the driver the policyholder? No
If No, Relationship of the Driver with the Insured Spouse
Does Driver Own Other Vehicles? No

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Change/cross lane
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

No
Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

No

Yes

Translator's ID Translator's phone number Translator's email Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Police Station Name

Police Station Phone No

Alt. Police Station Phone No

Police Station Address

Was notice of intended Prosecution given?

Yes

Traffic Police

(Phone) +65-65470000

(Fax) +65-65474900

10 Ubi Avenue 3 Singapore 408865

CIRCUMSTANCES OF ACCIDENT

If yes, against whom?

REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?

Yes No

Accident report SA2924CCM003

Page 2 of 27

DETAILS OF OTHER VEHICLE PROPERTY 1

| Vehicle Registration Number | QX527U |
|---|------------|
| Vehicle Manufacturer | - |
| Vehicle Model | 144 |
| Vehicle Variant | - |
| Vehicle Colour | - |
| Vehicle Category | Government |
| Name of Driver | - |
| Contact Number | - |
| Address | - |
| Address complement | - |
| Postcode | _ |
| Insurance Company Name | - |
| Nature Of Damage | - |
| Details of property damaged in accident | _ |
| No. Of Passenger (Including Driver) | |

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be as truthful and accurate as possible. Any will unisrepresentation or withtrolling of material tacts may allow insurance companies to reputiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- 6. This report will be forwarded by the insurers to the GBA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the tedgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insuter, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' tawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

- (ii) investigating the accident analor my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable faw in administering, processing, harraking and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lavyers/law firms, imagiate permitted to collectuse, disclose and/or process my Personal Information for one or more of the above Purposes, and


(c) my Personal Information mayican be disclosed by any of the Insurers and/or GIA to their find-party service providers or agents (including their fawyers/law firms), which may be said outside of Singapore, for one or more of the above Purposes

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the collopholder) / Date & Time

Wilnessed by Report Post of Responsition (Name as in NRICAD Card)

Sketch Plan



| Describe Circumstance of the Accident Date of Accident: 12 Dec 2024 Time: QS.00 am Location: CTE (A/R) Stop Rad Ando Prectives) My Venicle A: SNA 6585T Venicle B: QX55TV Venicle C: I was officially my car swaf6585 T along CTE (A/R) stopped road into Port (Tu R)). Specializativy along Jalan Too Rayth, was behind Vehicle B wich is a police for B chilar turn both though Too Payth for Sc I carthough the Stopped Too Payth stip tenand the strong that large and knowed have from Too Payth stip tenand the strong that large and back light Rate carthod in the book with side scart door B clauraged and back light Rate carthod in the book with side scart door B clauraged and back light Rate carthod in the book with side scart door B clauraged and back light Rate carthod A the Leal Police Report Nos. T Some 1212 / 71176 Claim OD/TP at At Lim Motor D Claim OD/TP at other workshop My Workshop: Workshop Brain Address Note: Please lake note that your insurer have a 1d days invetering for you to submit our damage chain under your compolicy Kindy check with your own insurer for more information. Deplaration Now gaster to foregoing particulars are true in every respect. | |
|--|--|
| Date of Accident: 12 Dec 2024 Time: Q8.01 am Location: CTE (APE) stip Rand add PreCitats) My Vehicle A: SWA6585T Vehicle B: QX557TV Vehicle C: I was driving my car SWA6585T along CTE (AVZ) a bread road into Pit (Tu A)). Specifically along John Tox Rayth, was behild behick B which B a Police Car B chiler turn by the thorard Tox Rayth Lare 6 to 1 continue toward RECTURS). B driver suddently changed Larre From two Papers high size toward the strength Larre and knowned high Rake screeting in the paper high size. Thy car back side sout dow B dawased and back light Rake screeting in the paper high Back wheel B also screeting. A flee Lail Police Report No. T [>00017P at Ah Lim Motor D Claim ODTP at other workshop Reporting Only Remarks: Please forward a copy of my effe accident Repair Back. My Workshop: Workshop Email Address Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident Repair Back. Note: Please forward a copy of my effe accident repair Back. Decription Toxic Affect Repair Back. Note: Please forward a copy of my effe accident repair Back. Note: Please forward a copy of my effe accident | scribe Circumstance of the Accident Loup Pole 35953 |
| I was driving my car SWA6515T along CTE (AVZ) along road into Pt (Tu A). Specifically along John Tox Rayth, line behind lookick B. which is a police car B chiler turn light thought Tox Rayth for 6 is 1 certificity toxond the CTUAS). B driver suddently changed Lang From two Payth size toxond the strength Lane and knowled my car on the see hight side. Ny car back side sant der B damaged and back light-Raba scratched inght back wheel is also scratched. Adae and Police Report No. T JONE 1212 / 7126 Claim OD/TP at At Lim Motor D Claim OD/TP at other workshop. Remarks: Please forward a copy of my effe accident Report Be My Workshop: Workshop Email Address Note. Please take note that your insurer have, a 14 days time frame for you to submit own damage claim under your own. Deplaration Deplaration | ate of Accident: 12 Dec 2024 Time: 08.00 am Location: CTE (AYE) Sho Road Auto PRECTURES |
| Claim OD/TP at Ah Lim Motor Diam OD/TP at other workshop Reporting Only Workshop Enrice Acceptance Accep | ly Vehicle A: SWA 6585T Vehicle B: QX 507U Vehicle C: |
| Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only | I was driving my car swalblist along CTE (AVZ) alighed road into life (Tu A). Specifically along John Toallayth. (was belied lightle B which is a police car B chiler turn light toward Toallayth Lar So I continue toward PIE (Twas). Bander suddenly changed Lane from Toallayth size toward the strongth Lane and knowled my car or the esternal right side. Ny car back side sout door B damaged and back light Ralpo scratched |
| Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop Reporting Only Remarks: Please forward a copy of my effic accident Report Re | hight back wheel is also econtched. |
| Remarks : Please forward a copy of my efficient Report for My Workshop : Workshop Email Address Note : Please take note that your insurer have a 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information Deplaration | Attached Police Report No. T/20241212/7126 |
| My Workshop : / Workshop Email Address Note: Please take note that your insurer have a 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information Deplaration | ☐ Claim OD/TP at Ah Lim Motor ☐ Claim OD/TP at other workshop ☐ Reporting Only |
| Workshop Email Address Note: Please take note that your insurer have a 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information. Deplaration | emarks : Please forward a copy of my efile accident Report la |
| Note: Please take note that your insurer have a 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information. Deplaration | My Workshop : |
| policy. Kindly check with your own insurer for more information Deplaration | |
| Deplaration | |
| Folicyholder's Signature (Date & Time Actuar Onver's Signature (if driver is not the policyholder) Witnessed by Ruporting Centre Personnel | Declaration t/We declare the foregoing particulars are true in every respect |

vJun2022

4





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20241212/7126

| DEDUBL | ∩≈ മ | TRAFFIC | ACCIDENT |
|--------|------|---------|----------|

| Date/Time Report Made: 12/12/2024 22:53 | | | Vide Report No.: Station Diary E/20241212/0048 | | | |
|---|---------------|--|---|-----------------|--|--|
| Informani | 's Particular | | | | | |
| Name of Informant: Hong Ching Chung | | | Address: 37 Chempaka Avenue SINGAPORE 349650 | | | |
| ID Type / ID No.: NRIC NO / S1611598C | | | Contact No.: Home/Office: Mobile: 92379913 | | | |
| Nationality: SINGAPORE CITIZEN | | | Email: cc9hong@gmail.com | | | |
| Sex: Age: Date of Birth; Male 61 03/10/1963 | | | Type of Informant: Vehicle Owner | | | |
| Race: Chinese | | | Language: English | | | |
| Occupation: Manufacturing manager | | | Driving Licence Information: Class: | Date of Expiry: | | |

| | of the Accident | Drink Drive: | Date/Time of Conidant | Trunc of Location | |
|-------------------|------------------------------|----------------------|---|---------------------------------|--|
| Type of Accident: | Non-Injury Police Vehicle | No | Date/Time of Accident: 12/12/2024 08:00 | Type of Location: Y-Junction | |
| Location: | | | | | |
| JALAN TENTERAI | A | | | | |
| | | | • | | |
| Treatite. | | Road Surface: Dry | | | |
| Traffic Flow: | | Traffic Control: | ic Control: Traffic | | |
| | | Not Controlled | ot Controlled Moderate | | |
| One Way | | 1400 COIN CACO | | | |

| Vehicle No. | hicle Involved Type | Make | Model | Color | Condition | No of Passenger |
|-------------|------------------------|--------|--------|-------|---------------------|-----------------|
| QX527U | Police Vehicle | INEXAC | MIJOEI | White | Slightly Damaged | 0 |
| SNA6585T | Motor car | BMW | 216 | Beige | Slightly Damaged | 0 |

| Details of Vehicle Insurance | | | | |
|------------------------------|---------------------------|-----------------|----------------|-------------|
| Vehicle No. | Insurance Company | Insurance No | Effective Date | Expiry Date |
| SNA6585T | EQ INSURANCE COMPANY LTD. | DMPPHQ24-006574 | 01/07/2024 | 30/06/2025 |
| | | | | |



T/20241212/7126

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

2 of 3 Report No. T/20241212/7126

CONTINUATION OF REPORT

| Details of Person | | | innolinime this labeler constant accordance | *************************************** | | |
|--|-----------------------|-----|---|---|---------------------------------|-----------------------------------|
| Any Pedestrian In | <u> </u> | | | | | |
| No. of Pedestrians | i Injured: NIL | | Use of Pede | estrian (| Crossin | g: NA |
| Driver | | | | | | |
| Name | TAN CHAI HAR | | - | ID No. | | S1624014A |
| Related Vehicle | SNA6585T (Motor car) | | | Contac | ct No. | 97803781 |
| Hospital/Clinic | NIL | | Class of Driving Licence & Expiry Date | | Class: 3 Date of Expiry: NIL | |
| Date Treatment | NIL Date I | | | arge | NIL | . k |
| No. of Days granted Medical Leave (MC) NIL | | | Degree of I | njury | NL | |
| Vehicle Owner | | | | | / | |
| Name | HONG CHING CHUNG | | | ID No. | | S1611598C |
| Related Vehicle | NIL | | | Contact No. | | 92379913 |
| Hospital/Clinic | NIL | | | Class of Driving Licence & Expiry Date | | Class: NIL Date of Expiry: NIL |
| Date Treatment | NIL. | | Date Disch | arge | NIL | - Lander- |
| No. of Days grant | ed Medical Leave (MC) | NIL | Degree of I | njury | NIL | |

Brief Details.

My wife (I/C# S1624014A - Tan Chai Har) was driving my car SNA6585T along CTE/AYE Slip road into PIE Tuas. Lamp pole location is: 359526F. To be more specific, my wife was driving along Jalan Toa Payoh towards Tuas. She was behind a police car QX527U on the right lane. Police car turned right towards Toa Payoh Lor 6. She continue on the same lane towards PIE Tuas. The Police car suddenly changed lane from Toa Payoh Slip road back and knocked my car at the right side back door.

My car right back passenger door is damaged. Right back light is scratched, Right back wheel is also scratched. The driver and passenger in the Police car both admitted that this is their fault. However, this involved Police car, so we waited until Traffic police arrived and recorded this case.

Case # is E/20241212/0048.

Investigation Officer is Mr. Fadil, contact number is: 65476845




Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000





3 of 3 Report No. T/20241212/7126

CONTINUATION OF REPORT

| Signature Of Officer Recording The Report Not applicable | Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required |
|--|--|
| Signature Of Interpreter: Not applicable | Date/Time: 12/12/2024 22:53 |
| Officer In Charge Of Case: TP / DDGVT / JOFILIANO BIN MOHAMED ALI Contact No.: 65476960 | Classification Of Case: |
| NP168 | |







EQ Insurance Company Limited 77 Robinson Road #12-01 Robinson 77 Singapore 052896 tel (65) 6223 9433 | www.eqinsurance.com.sg ree no. 1978-03490-N



CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION) (REPUBLIC OF SINGAPORE)

THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) BULES, 1996 EDITION(REPUBLIC OF SINGAPORE)
OR ANY AMENOMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

PRIVATE CAR Comprehensive

Certificate No.: DMPPHQ24-006574

1. Index Mark and Registration Number of Vehicles SMAGSRST

2. Engine No. and Chassis No. 40506362B38A15A / W8A2X920407H97821

3. Name of Policyholder HOME CHING CHING

4. Effective Date of the Commencement of Insurance for the purpose of the Act

S. Date of Expiry of Insurance 30/05/2025

6. Person or Classes of Persons entitled to drive*

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been permitted and is not disqualified by order of a Court of law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act has not been cancelled at the time of accident loss or damage.

7. Limitations as to use*

Use for social, domestic and pleasure purposes and for the Policyholder's

The policy does not cover:
(a) use for hire or reward
(b) use for racing, pace-making, reliability trials or speed testing

(c) use for the carriage of goods (other than samples) in connection with any trade or business

(d) use for any purpose in connection with the Motor Trade

*Limitations rendered inoperative by Section 8 of the Motor vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1967 (Malaysia), are not to be included under these headings.

INSE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or and Amendment, Act or Acts passed in substitution thereof.

HP: DBS Finance Ltd misjb/HO/A000112/Teo Shao Wei

A Member of Citystate

Authorised Signatory EQ Insurance Company Limited

Form: MX2

Unnamed Drivers

Insured/Named Oriver SGD500.00

EQI Mator Accident

Hottine

6311 3211

SGD1.000.00

Additional SGD3,000.00