ASS, REC. BY:

Steve

## KEF:

## CS/LIP24120259/Enh3

## ASSIGNMENT

From: Date:	Veh No: GBH 5434H Yr Regn: 06/07/2018
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Mitsubishi L200 c.c 2477
at Workshop m/s	Colour White A/C: Insured / Std / NI / NA
of	Sp.Reading 78356 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: MMCJJKL20JH012334
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205R16C
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	тоуотуоко ог GT Radial
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 07/12/24 D.O.I. 18/12/24
Lum Sum: % 3 Val.: Yes or No	Survey held at Liu`s Brother
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT  Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
	The O/O / Chassis Haile / Body Chastare and Chastare
Date / Time Action / Instruction  MV - \$39k	
- IVI V QOSK	
Steve confirmed lump sum \$300 (red, \$5998, 66%)	00 and 5 days
(160, \$555, 6670)	
·	
	Days Of Repair: 5
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5  Resurvey No. of Trip: Survey Fee:
1) : Final Report	Transportation:
Add Fe	
2)	: Interview (\$ ) Photos
Report Formal:	: Tech. Invs (\$ ) Others
Lump Sum / LB J: CF	: Weel and (%
The state of the s	7074