

Steve

CS/ICS24120260/Eqp3

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:	_____		
IDAC Accident Rpt:	_____	Consistent? :	Yes or No
GIA / PR Seen:	_____	Consistent? :	Yes or No
Est. Repairs:	_____ days	Res.:	Yes or No
Lum Sum:	_____ %	3 Val.:	Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Veh No: SNL7574K Yr Regn: 31 Jul 2023

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HONDA FIT C.C. 1498

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 86138 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: GR11106502 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 185/60R15

R: "

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TRIANGLE

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 14/12/24 D.O.I. 18/12/24

Survey held at HHHB PTE LTD

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front RH

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
Date/Time, File Return to?

2)

Rep. Format :

London School of Economics

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL