REF: CS/INC24120263/Aqh3

ASSIGNMENT

From: Date:

Estimate Amount:

OD / TP / TP RES / OD RES / EVA / INV / MV

To Insured Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKD617SM Yr Regn: 2011 / Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Volkswagen Scirroco c.c 1390

Colour Yellow. A/C: Insured / Std / Nil / N.A

Sp.Reading 287344. T/Radio: Insured / Std / Nil / N.A

Eng/No:

C/No: WVWZZZ13ZCV014347

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/40R18.

R: 235/40R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	18/12/24.

Survey held at JL Perfect.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC
	LS $7000, 7 days (Red $22039.08, 76%)
	MV :
	PV :
	Nett :

COE Expiry : 21/12/2031

Estimate given during 1st Survey : Yes (✓) No ( )

5837

Date/Time, File Pass to? ☐ : Preli. Report

1) 20/02 Typist ☐ : Final Report

Date/Time, File Return to?

2)

Report Format : TP

Days Of Repair: 7

Resurvey No. of Trip: 3

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: B + RS. S

Photos

Others