ASS, REC. BY:

Steve

## - KEF:

## CS/LIP24120281/Enh3

## ASSIGNMENT

From: Date:	Veh No: SLP8953X Yr Regn: 21 Jun 2017
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: MAZDA 3 SEDAN c.c 1496
at Workshop m/s	Colour Grey A/C: Insured / Std / NI / NA
of	Sp.Reading 658972 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: JM6BN22A8H0154848
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205/60R16
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or WESTLAKE
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 5 mm L/Bal. 5 mm
Est. Repairs: 5 days Res.: Yes or No	D.O.A. 17/12/24 D.O.I. <u>07/01/25</u>
Lum Sum: % 3 Val.: Yes or No	Survey held at My Car Consultant
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	" to black to collision
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV - \$32k	
Steve finalize \$3900.00 (L/S, befo	ore GST). 5 days.
(red, \$11348.12, 74%)	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 5
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	
	: Interview (\$) Photos
Report Formai:	: Tech. Invs (\$) Others
Lump Sum / LE J: (%)	: Weel end (\$)
	TOTAL