

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN		Ref:	CS/INC24120286/Anh3m4(N)		
	75 BRAS BASAH FINCOME CENTRES		Date:	25/02/2025		
	ATTN: JEFF LIN			Code:	INC	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	GBD 2331L	Veh. Inspected	t	SJW 5963Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1309002-001	Excess (\$)		0.00	
	Assign From	ANNA YEO	Assign Date		19/12/2024	
2. Vehicle Particulars & Condition						
	Make & Model	VOLKSWAGEN GOLF GTI	c.c		1984	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	WVWZZZ1KZAW268160	Colour		BLUE	
	Odometer	213553 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40R18	GOODYEAR		6 mm	
	L/H Front Tyre	245/40R18	GOODYEAR		6 mm	
	R/H Rear Tyre	245/40R18	GOODYEAR		6 mm	
	L/H Rear Tyre	245/40R18	GOODYEAR		6 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
					§ *	
5.	5. General Information					
	Accident Date	17/12/2024	Inspect Date /	Time	19/12/2024 ( 02:23 PM )	
	Survey held at JL PERFECT AUTOWORK PTE LTD  8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875					
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•					