



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24120288/Avh3e2(N)

Date: 02/04/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMX 6958S	Veh. Inspected	SNL 5348K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1308774-002	Excess (\$)	0.00
Assign From	JULIE	Assign Date	19/12/2024

2. Vehicle Particulars & Condition

Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	JM6BP2SAAP1152507	Colour	BLACK
Odometer	59700 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S. REAR N/S
PORTION AND UNDERCARRIAGE.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/12/2024	Inspect Date / Time	19/12/2024 (03:09 PM)
Survey held at	ELITE AUTO RESTORATION PTE LTD 23 KAKI BUKIT AVE 4 #04-01, AAS KAKI BUKIT CENTRE SINGAPORE 415933		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **26 Working Days**