

ASS. REC. BY:

REF: MSG-1 CS/MSG24120293/Kvp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SNQ 3752M

Policy No. 1003519432


Claims No. 385409

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$121K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: PNG 1428R

Yr Regn: 071 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota

Altis

c.c.

1798

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

NR 2B83BE4 00009298

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Selima 225/45 R17

R: Turismo

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

4

mm

L/Bal.

3

mm

L/Bal.

4

mm

D.O.A.

15/12/24

D.O.I.

19/12/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S & N/S Rr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/11/21 Rm @ 3600h Colw (6310.90, 63%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fees

Others

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)
Tel: 93911482

Not Notation
C/Ly & 3600/-
Merry After Rain
5 days

TO :	DATE : 19-Dec-24
ATTENTION : MOTOR CLAIMS DEPT	JOB TYPE : T/P CLAIM
<u>VEHICLE DETAILS</u>	
:	VEHICLE NO : SNG1428R
:	MODEL : TOYOTA ALTIS

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>798 CM</i>	1	\$ 850.00	\$ 850.00
2	REAR BUMPER SENSOR <i>Sm</i>	2	\$ 389.10	\$ 778.20
3	REAR BUMPER RETAINER LH <i>Sm</i>	1	\$ 105.00	\$ 105.00
4	REAR BUMPER REINFORCEMENT <i>R</i>	1	\$ 397.00	\$ 397.00
5	REAR BUMPER REFLECTOR LH <i>Sm</i>	1	\$ 68.00	\$ 68.00
6	TAILAMP LH <i>Sm</i>	1	\$ 712.00	\$ 712.00
7	REAR FENDER LH	1	\$ <i>R</i> 1,025.00	\$ 1,025.00
8	REAR FENDER COWLING LH	1	\$ <i>Sm</i> 212.00	\$ 212.00
9	REAR DOOR LH <i>Del/wap</i>	1	\$ 1,258.00	\$ 1,258.00
10	REAR WHEEL BEARING LH <i>nm</i>	1	\$ 251.00	\$ 251.00
11	REAR BLINDSPORT SENSOR LH <i>Sm</i>	1	\$ 1,125.00	\$ 1,125.00

TOTAL PRICE \$ 6,781.20
LESS 25% \$ 1,695.30
SUB TOTAL PRICE \$ 5,085.90

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR SPORT RIM LH <i>Del</i>	1	\$ 1,200.00	\$ 1,200.00
2	REAR TYRE LH	1	\$ <i>Sm</i> 250.00	\$ 250.00
3	REAR DOOR STICKER LH	1	\$ <i>Sm</i> 500.00	\$ 500.00
4	REAR BUMPER CLIPS	10	\$ <i>Sm</i> 6.50	\$ 65.00
5	REAR BUMPER STICKER <i>nm</i>	1	\$ 150.00	\$ 150.00

TOTAL \$ 2,165.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$800.00	500l	
2	TO SPRAY PAINT AFFECTED AREA	\$1,000.00	800l	
3	REMOVE AND REFIX REAR UNDERCARRIAGE	na \$300.00	X	
4	CONDUCT WHEEL ALIGNMENT	\$150.00	60l	
5	TUFF COAT	\$250.00	30l	
6	WIRING CHECK	\$80.00	20l	
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$80.00	50l	

TOTAL

\$2,660.00

TOTAL PARTS COST : \$ 7,250.90
TOTAL LABOUR COST : \$ 2,660.00
TOTAL REPAIR COST : \$ 9,910.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: