

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 199607196R GS1 Reg. No. 19-9607196-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI24120294/Evp3e2(N)	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	24/01/2025	
	ATTN: CHEN HOV	V	Co	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJH 9774E	Veh. Inspected		SLN 7140S	
	Policy No.	P11114836R00	Coverage (\$)		0.00	
	Claim No.	C10033541/CH	Excess (\$)		0.00	
	Assign From	CHEN HOW	Assign Date		19/12/2024	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 3	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JM6BN22A8H0151781	Colour		BLUE	
	Odometer	168655 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/60 R16	TOURADOR		6 mm	
	L/H Front Tyre	205/60 R16	TOURADOR		6 mm	
	R/H Rear Tyre	205/60 R16	TOURADOR		6 mm	
	L/H Rear Tyre	205/60 R16	TOURADOR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	17/12/2024	Inspection Date		09/01/2025	
	Survey held at MY CAR CONSULTANT PTE LTD					
		60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	5b. Estimate Days of Repair					

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: