

MY CAR CONSULTANT PTE LTD
(Co Reg. No. 201605878Z)
60 JALAN LAM HUAT, CARROS CENTRE
#05-68 (S737869)

TO	: BUDGET DIRECT	DATE	: 9-Jan-25
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
VEHICLE DETAILS			
:		VEHICLE NO	: SLN7140S
:		MODEL	: MAZDA 3

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER / BR	1	\$ 895.00	\$ 895.00
2	FRONT BUMPER SIDE RETAINER LH / BR	1	\$ 86.50	\$ 86.50
3	HEADLAMP LH / BR	1	\$ 1,285.00	\$ 1,285.00
4	FRONT FENDER LH / M	1	\$ 698.20	\$ 698.20
5	FRONT FENDER COWLING LH / TN	1	\$ 251.00	\$ 251.00
6	FRONT DOOR LH X R	1	\$ 1,025.00	\$ 1,025.00
7	SIDE MIRROR LH X R	1	\$ 701.20	\$ 701.20
8	FRONT KNUCKLE ARM X M	1	\$ 845.00	\$ 845.00
9	FRONT KNUCKLE ARM BEARING X M	1	\$ 226.00	\$ 226.00

TOTAL PRICE \$ 6,012.90
LESS 20% \$ 1,202.58
SUB TOTAL PRICE \$ 4,810.32

3,144.70
-20%
2,515.76

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP SET / M	1	\$ 65.00	\$ 65.00
2	FRONT WHEEL RIM LH X M	1	\$ 850.00	\$ 800.00

TOTAL \$ 865.00

30

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	CUT OFF AND REPLACE FRONT SUPPORT PANEL. RESTRUCTURE FRONT CRASH MANAGEMENT COMPONENT AND RENEW OTHER DAMAGE PARTS.	\$ 500.00	499	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 800.00	699	
3	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 300.00	X	
4	CONDUCT FULL WHEEL ALIGNMENT	\$ 150.00	X	
5	ADJUST AND FOCUS FRONT LIGHTING SYSTEM. PERFORM HEADLAMP ADJUSTMENT TO POSITION	\$ 80.00	30	

930

TOTAL

\$ 1,830.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,675.32
TOTAL LABOUR COST : \$ 1,830.00
TOTAL REPAIR COST : \$ 7,505.32

3,475.76

L/S - 2,780.60
= 2800

Steve (LKK)
9/1/25, 4.01 pm
m l
L/S
L AL R
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: