



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24070028/Anh3m4
50 RAFFLES PLACE #03-03	Date:	08/08/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMF 6888E	Veh. Inspected	SHC 1563A
Policy No.	-	Coverage	0
Claim No.	CMTD2402154/THE	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	01/07/2024

### 2. Vehicle Details

Make & Model	HYUNDAI AE IONIQ	C.C	1580
Engine No.	G4LEKU408926	Year of Reg.	11/03/2020
Chassis No.	KMHC851CVLU189939	Colour	BLUE
Odometer	564863 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	WESTLAKE	6
L/H Front Tyre	195/65R15	WESTLAKE	6
R/H Rear Tyre	195/65R15	WESTLAKE	6
L/H Rear Tyre	195/65R15	WESTLAKE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	29/06/2024	Inspection Date	01/07/2024
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days