

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	SURANCE (S) PTE LTD		Ref:	CS/CTI24120334/Knh3e2(N)	
	3 ANSON ROAD #7 SPRINGLEAF TOW	16-00 VERSINGAPORE 079909		Date:	04/02/2025	
	ATTN: LYNN KHON	NG		Code:	CTI	
1.	. Policy Particulars :- OWN DAMAGE					
	Insured Veh.		Veh. Inspected	d	SNE 4441S	
	Policy No.	DMPCSNW00105092400	Coverage (\$)		0.00	
	Claim No.	SNM24D207160	Excess (\$)		0.00	
	Assign From	LYNN KHONG	Assign Date		23/12/2024	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ E200 (A)	c.c		1991	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	WDD2130422A468163	Colour		METALLIC GREY	
	Odometer	95328 KM	Steering		JAMMED	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/40 R19	GOODYEAR		8 mm	
	L/H Front Tyre	245/40 R19	GOODYEAR		8 mm	
	R/H Rear Tyre	275/35 R19	GOODYEAR		8 mm	
	L/H Rear Tyre	275/35 R19	GOODYEAR		8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	19/12/2024	Inspection Dat	e	23/12/2024	
	Survey held at	DING AUTO PTE LTD				
		60 JLN LAM HUAT CARROS CENTRE #06-46/47 SINGAPORE 737869				
5a.	Remarks					
	A)THE MARKET VALUE IS S\$137,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		22 Worl	king Days	