

ASS. REC. BY:

REF: *MS6/*

CS | *MS6 24120336* / *Kn p3*

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____ *My Car*

of _____ *961K*

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *\$124K*

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: *05* days Res.: Yes or No

Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SNM 4751E* Yr Regn: *09, 23*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *Toy Altas* c.c. *1798*

Colour: *M. Grey* A/C: Insured / Std / NI / NA

Sp. Reading: *91710* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *MR 2BZ 3BE 400012640*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / R/Rim or

Tyre Size: F: _____ *225/45ZR17*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____ *Fire 79*

Front _____ Rear _____

R/Bal. *9* mm R/Bal. *9* mm

L/Bal. *9* mm L/Bal. *9* mm

D.O.A. *19/12/24* D.O.I. *23/12/2024*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Km body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>1</i>	<i>EM not ready</i>
<i>28/12</i>	<i>LT Pump @ 4450/r Coln (Red. \$6146, 58%)</i>

Date/Time, File Pass to? : Prell. Report

: Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: *5*

Resurvey No. of Trlp: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S - RS. \$I _____

Fuel: _____

Others: _____

TOTAL: _____

Report Format :

Lump Sum / I.B.I: (\$ _____)

MY CAR CONSULTANT PTE LTD
 (Co Reg. No. 201605878Z)
 60 JALAN LAM HUAT, CARROS CENTRE
 #05-68 (S737869)
 Tel: 93911482

NOT NOTIFIED
 11pm @ 4450hr
 Rainy After Rain
 5 days

TO :	DATE :	23-Dec-24
ATTENTION :	MOTOR CLAIMS DEPT	JOB TYPE : T/P CLAIM
		<u>VEHICLE DETAILS</u>
		VEHICLE NO : SNM4751E
		MODEL : TOYOTA ALTIS

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	BONNET	1	\$ 1,125.00	\$ 12 1,125.00
2	FRONT BUMPER <i>533</i>	<i>Per 1 CM</i>	\$ 821.00	\$ 821.00
3	FRONT BUMPER LOWER	<i>Per 1</i>	\$ 582.00	\$ 582.00
4	FRONT BUMPER SIDE RETAINER LH	<i>CM 1</i>	\$ 98.00	\$ 98.00
5	FRONT BUMPER SIDE GARNISH LH	<i>Per 1</i>	\$ 212.00	\$ 212.00
6	FRONT BUMPER FOGLAMP COVER LH	<i>1h 1</i>	\$ 198.00	\$ 198.00
7	SIDE MIRROR LH	<i>Cover CM 1</i>	\$ R 698.00	\$ 698.00
8	FRONT FENDER LH <i>698</i>	1	\$ 798.00	\$ B 798.00
9	FRONT FENDER INNER SHIELD LH	1	\$ 198.00	\$ CM 198.00
10	FRONT FENDER EMBLEM 'HYBRID' LH	1	\$ 52.00	\$ Na 52.00
11	FRONT GRILLE C/W CHROME	<i>Per 1</i>	\$ 512.00	\$ 512.00
12	HEADLAMP LH <i>2598</i>	<i>mg CM 1</i>	\$ 3,598.00	\$ 3,598.00

TOTAL PRICE \$ 8,892.00
 LESS 25% \$ 2,223.00
 SUB TOTAL PRICE \$ 6,669.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS	10	\$ 6.50	\$ Na 65.00
2	FRONT BUMPER LOWER GRILLE CLIP	8	\$ 6.50	\$ Na 52.00
3	FRONT TYRE LH	1	\$ Per 300.00	\$ 300.00
4	FRONT SPORTS RIM	1	\$ 1,200.00	\$ Per 1,200.00

TOTAL \$ 1,617.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$800.00		500h
2	SPRAY PAINTING TO AFFECTED AREA	\$800.00		600h
4	CONDUCT WHEEL ALIGNMENT	\$150.00		60h
5	WIRING CHECK	\$200.00		20h
6	RESET ENGINE TROUBLE CODE	\$300.00	nn	X
7	REFOCUS HEADLAMP BEAM	\$60.00		X

TOTAL

\$2,310.00

TOTAL PARTS COST : \$ 8,286.00
TOTAL LABOUR COST : \$ 2,310.00
TOTAL REPAIR COST : \$ 10,596.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: