

REF:

### ASSIGNMENT

FRONT \_\_\_\_\_ Date: \_\_\_\_\_  
 Estin <sup>Estimate</sup> \_\_\_\_\_  
 OD / ~~TP~~ / TP RES / CD RES / EVA / INV / MV  
 To in <sup>Vehicle</sup> Vehicle No: \_\_\_\_\_  
 at <sup>W/O</sup> \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No \_\_\_\_\_  
 Claim No \_\_\_\_\_  
 Sum <sup>INS</sup> \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh \_\_\_\_\_  
 (Policy Condition)

Veh No: SMK4104X Yr Regn: 2019, April  
 Type: M.Cap / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda Fit. C.D. 1496  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading: 449026 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GP51335614  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 185/60R15  
 R: 185/60R15

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Kapsen

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Bal. 06 mm R/Bal. 06 mm  
 L/Bal. 06 mm L/Bal. 06 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 24/12/24  
 Survey held at Twin Car  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>PP inc</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 E-mail: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 Photos: \_\_\_\_\_  
 Others: \_\_\_\_\_  
 Addl Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Inve (\$ \_\_\_\_\_)