



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 ATTN: CHEN HOW			Ref: CS/AGI24120365/Uvp3e2(N) Date: 06/01/2025 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLX 4287U	Veh. Inspected	YN 2770C	
Policy No.	P10709110R02	Coverage (\$)	0.00	
Claim No.	C10033441/CH	Excess (\$)	0.00	
Assign From	CHEN HOW	Assign Date	24/12/2024	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI FE85 (M)	c.c	4899	
Engine No.	HIDDEN	Year of Reg.	2011	
Chassis No.	FE85DJA20125	Colour	RED / BLUE	
Odometer	342494 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/75 R17.5	LEAO	6 mm	
L/H Front Tyre	215/75 R17.5	LEAO	6 mm	
R/H Rear Tyre	215/75 R17.5 (D)	LEAO	6/6 mm	
L/H Rear Tyre	215/75 R17.5 (D)	LEAO	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/12/2024	Inspection Date	26/12/2024	
Survey held at	SPEEDWERKZ PTE LTD 1 KAKI BUKIT AVE 6 #01-73, AUTOBAY @KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	