

Your Ref: 24/24/24/VC11/411651

Date: 17th Jul 2024

Our Ref: CS1/LPM24070034/Evh3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank

No. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLC 1950T

INSURED VEHICLE: JQX 6933

ACCIDENT DATE: 21/03/2024

We thank you for your instruction on 01/07/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLC 1950T from M/s ST Appraisal Services.
- b) Final Repair Bill of SLC 1950T from M/s YK Supreme Autowerkz Pte Ltd.
- c) Singapore Accident Statement and Police Report of Vehicles SLC 1950T.
- d) Colour damaged vehicle photographs of SLC 1950T.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SLC 1950T
Make & Model	: Toyota Corolla Altis 1.6L CVT
Year of Registration	: 2016
Chassis Number	: MR053REH104543376
Engine Capacity	: 1598 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.